

## APPROVED LAND CORNER

P.A. 345 OF 1990  
MIDLAND COUNTY

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Midland County Remonumentation

488

For Corners in

Midland

(County)

Located In:

Corner Code#:

1. Public Land Survey

T. 16N R. 1W I-10

T. \_\_\_\_\_ R. \_\_\_\_\_

T. \_\_\_\_\_ R. \_\_\_\_\_

2. Public Controlling

S. \_\_\_\_\_ T. \_\_\_\_\_ R. SURVEY &

in Section

S. \_\_\_\_\_ T. \_\_\_\_\_ R. REMONUMENTATION

3. Miscellaneous

S. \_\_\_\_\_ T. \_\_\_\_\_ R. \_\_\_\_\_

Property in Section

S. \_\_\_\_\_ T. \_\_\_\_\_ R. FEB 23 2001

4. Lot No. \_\_\_\_\_

Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

SECTION \_\_\_\_\_

STATE OF MICHIGAN  
MIDLAND COUNTY  
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES  
REGISTER OF DEEDS

Register of Deeds Stamp &amp; File Number

I, Mark R. Robison, in a field survey on July 5, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1852, Burt

N09°E 40.07 1/4 Cor (I-10)

N23° E 80.96 Old Cor. 22, 23, 26, 27

Y. Pine 22" S30°E, 25 LINKS

Y. Pine 16" N70°W, 25 LINKS

1992, Jones, LCRC #725

Fd 3/4" pipe called for in previous surveys

S45°E, 66.47' N &amp; T in 15" Oak

N45°E, 65.6' C.L. B.Oak in Lawn

N55°W, 65.20' - N &amp; T in 18" Oak

No C.S.R Records

1997, Jones (132) 5-480

Fd 3/4" Ayres Capped Pipe

S40°W, 65.06 6" Oak

N70°W, 65.45 18" Oak

N30°E, 125.50 T.P.

S45°E, 66.48 18" Oak

Undated, Field Notes from Ayres office.

ENE 106.53 30" Oak

SE 66.1 6" Oak

SW 99.7 T.P.

NW 90.9 T.P.

Meas. North 2693.52

Meas. South 2644.62

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1" x 18" Capped Pipe with 3/8" x 18" Pointed rod 0.3' E.N.E. of pipe. Accepted position of pipe. Found all 1992 witnesses and capped pipe 33 feet East. Meas. North 2693.20 feet to I-9. Accepted as best available evidence of the perpetuation of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" pipe with brass cap stamped "Midland County Remon Corner, P.S #27458".

Witnesses:

N69°W, 65.48' - N &amp; T in 18" Oak (OBT)

N58°E, 65.6' - Cen. Of 16" Oak in yard (OBT)

S49°E, 66.50' - N &amp; T in 18" Oak (OBT)

N55°W, 67.28' - N &amp; T in 11" North Trunk of 5 Oaks

Signed by

Surveyor's Michigan License No. 27458

