

## APPROVED LAND CORNER

P.A. 345 OF 1990  
MIDLAND COUNTY

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Midland County Remonumentation

490

For Corners in

Midland

(County)

Located In:

Corner Code#:

1. Public Land Survey

T. 16N R. 1W K-5T.        R.       T.        R.       2. Public Controlling  
in SectionS.        T.        R.       S.        T.        R.       

3. Miscellaneous

S.        T.        R.       

Property in Section

S.        T.        R.       4. Lot No.       , Recorded Plat       5. Private Claims       SECTION       STATE OF MICHIGAN  
MIDLAND COUNTY  
REMONUMENTATION & FILED

10/6/2000 10:36:48 AM

SCOTT I. HAINES  
REGISTER OF DEEDS

Register of Deeds Stamp &amp; File Number

I, Mark R. Robison, in a field survey on July 5, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below.

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1852, Burt

Set Cor 11-12-13-14

Hemlock 7" S63°W, 24 LINKS

Hemlock 28" N08°E, 28 LINKS

1987, Jones, (132) 4-36

References Corner - No Witnesses

No C.S.R. Records

1993, Lapham, LCRC #737

Fd 1/2" rod in Mon. Box

N50°E, 71.70' N &amp; T in P.P.

S25°E, 76.32' N &amp; T in P.P.

S25°W, 93.72' Spike in P.P.

N45°W, 54.10' Spike in 36" Maple

1998, Lapham Assoc.

Fd 1/2" rod in Mon. Box

N45°W, 57.3' Spike in P.P.

N60°W, 118.90' Spike in P.P.

20°W, 65.60' N. end Conc. Hdwl.

S20°E, 65.12' N. end Conc. Hdwl.

1975, Schafer, (132) 1-851

Mon. Box - No Witnesses

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 1/2" x 30" re-rod (badly rusted) along 1 1/2" x 1/4" bar at 18" deep in Mon. Box. Found three 1993 witnesses. It appears the 1998 witnesses are for a different corner. Set 3/4" x 18" pipe along side bar at position of 1/2" re-rod. Meas. North 2623.84 to K-4. Meas. South 5250.26 to K-7. Accepted position of 1/2" re-rod as best available evidence of the perpetuation of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" pipe with brass cap stamped "Midland County Remon Corner, P.S. #27458" in Mon. Box.

Witnesses:

N 68°E, 71.60' - N &amp; T in P.P. (OBT)

S60°E, 82.30' - N &amp; T in 24" Apple

S24°E, 76.28' - N &amp; T in Guy Pole (OBT)

S26°W, 93.69' - N &amp; T in P.P. (OBT)

Signed by

Mark R. Robison

Date

9-15-2000Surveyor's Michigan License No. 27458

FORM APPROVED BY MICHIGAN STATE BOARD OF SURVEYORS, JAN. 28, 1971



REVISED MAY 14, 1975  
REVISED JAN., 1983