APPROVED LAND CORNER

P.A. 345 OF 1990 MIDLAND COUNTY

8/34/00 AKZ

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Midland County Remonumentation

	_	_
	a	-2
- / 1	•	
-	• .	-

		
For Corners in		
Midland		
(County)	Located In: Corner Code#:	STATE OF MICHIGAN
		HIDLAND COUNTY
1. Public Land Survey	T. <u>16N</u> R. <u>1W</u> <u>K-6</u>	REMONUMENTATION & FILED
·	T R SURVEY &	
	T.—RREMONUMENTAT	10/6/2000 10:36:48 AN
2. Public Controlling	S. T. R. VIOIVIEIVIA	IOIN
in Section	S. T. R. FED 9 and	SCOTT I. HAINES
3. Miscellaneous	S. T. R. PED & 3 ZUUT	REGISTER OF DEEDS
Property in Section	S. T. R.	
4. Lot No	Recorded Plat SECTION	Register of Deeds Stamp & File Numbe
5. Private Claims		, ,
)		

1, Mark R. Robison, in a field survey on July 5, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1852, Burt 34.72 1/4 Sec Post Aspen 8" S76°E Sugar 8" N46°W, 27 LINKS

No C.S.R. Records

1978, Ankrom, LCRC #442
Set 1/2" rebar & cap on line and
½ way between NW & SW corner section.
N80°E, 32.70' Fence Cor
S80°W, 35.19' 4" Elm
2' East of C.L. Road

NOTE: GLO notes are as follows: S49W, corrected between 13 & 14 39.72 1/4 Sec Post S56W 79.59 Cor Sec's 13-14-23 & 24

Cannot accept Ankrom position, i.e., N1/2 39.72 S1/2 39.87 with a 0° 07' deflection per GLO notes.

B. Description of corner evidence found and/or method applied in restoring or re-establishing comer:

Found 5/8" iron set by Ankron 5.7' S.S.W. of position established per G.L.O. i.e., Ankrom set corner mid-way on line between Sec. Cors. NOT per G.L.O. notes. Considered corner lost and set position 2.67' East of mean line K-5 to K-7, and 2620.18' South of K-5, and 2630.08' North of K-7. Accepted this as the proper re-establishment of the original position of the corner. Removed Ankrom corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" pipe with brass cap stamped "Midland County Remon Corner, P.S. #27458" in Mon. Box. Witnesses:

West, 2.67' - Mean Sec. Line N38°E, 68.65' - N & T in 6" Birch N80°E, 43.20' - N & T in 10" Pine S18°E, 84.90 - N & T in Pine

Signed by Amu Q. (23, S1 Surveyor's Michigan License No. 27458 MARK R.
ROBISON
PROFESSIONAL
SURVEYOR
No.
27458

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 197