APPROVED LAND CORNER

AND CORNER RECORDATION CERTIFICATE

P.A. 345 OF 1990 MIDLAND COUNTY

Filing Requirement of Act 74, Mich. P.A. 1970 Midland County Remonumentation

8/24/	100	0	10
For Corners	in	7	

STATE OF MICHIGAN HIDLAND COUNTY REHONUMENTATION & FILED

497

Midland Located In: Corner Code#: (County) 1. Public Land Survey T. 16N R. 2W F-3 Т SURVEY & 2. Public Controlling T. R. REMonumentation in Section T. R. Т. R FEB 23 2001 Property in Section T. R.

10/6/2000 10:36:48 AM SCOTT I. HAINES REBISTER OF DEEDS

3. Miscellaneous

4. Lot No. Recorded Plat Private Claims

Register of Deeds Stamp & File Number

I, Mark R. Robison, in a field survey on July 7, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

10 18 16 15 20 21 23 10-30 29 28 27 26 25 35

BCDEFGHI

A. Description of original monument and accessories and/or subsequent restoration:

1832, Wright, Pine 14" N55°E, 3 LINKS Maple 9" S35°W, 53 LINKS

Gibbs, 1901 C.S.R Set in survey of Sec. 9 Meas. West 40.00 Meas. East 39.98

1977, Lapham, LCRC #415 Fd Mag. Reading in asphalt Set N & T North 37.4 6" Post South 31.5 6" Post S30°E, 40.3 6" Post

SECTION

1986, Lapham, LCRC #614 Fd 3/4" Pipe N10°W, 35.75 P.P. N35°W, 67.65' 12" Tw. Oak South 30.5 Fence Corner

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found 3/4" x 11" pipe over 1/2" rebar in Mon Box. in C.L. asphalt pym't. Found two 1977 witnesses. Meas. East 2645.16 to G-3. Meas. West 2643 to approximate int. of C.L. (No corner found). Fence lines to North and South from corner. Accepted 1/2" rebar as best available evidence of the perpetuation of the original position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 18" pipe with brass cap stamped "Midland County Remon Corner. P.S. #27458" in Mon. Box. Witnesses:

North, 59.34' - N & T in 8" Elm S70°E, 73.68' - N & T in 5" Elm S10°W, 40.30' - N & T in 6" Elm North 37.30' - N & T in 6" post (OBT)

Surveyor's Michigan License No.

Mark R. ROBISON ROFESSIONAL SURVEYOR No. 27459 SESSION

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN.28, 197