

REMON CORNER M-9, WARREN TWP.
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

550

For corners in

Midland
(County)

Located in: Corner Code #

1. Public Land Survey

T 16N R 2W M-9

T R

T R

T R

2. Property Controlling
in Section

S T R SURVEY &

S T R REMONUMENTATION

3. Miscellaneous
Property in Sec.

S T R

S T R FEB 23 2001

4. Lot No. _____ Recorded Plat _____ SECTION _____

5. Private Claims _____

I, RODNEY CLAYPOOL, in a field survey on June 23, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-9 Corner common to Sections 24 and 25 on East townline

Survey by Glo, 1830's, set post
Survey by MDOT, 1937, used corner
Survey by M. Hunter, 1958, 1969, found monument box
Survey by P. Lapham, 1974, found iron in monument box
LCRC by P. Lapham, 1974, iron in monument box

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-9 Corner common to Sections 24 and 25 on East townline

Found $\frac{3}{4}$ " pipe in monument box at position per surveys by MDOT, M. Hunter, P. Lapham and LCRC by P. Lapham.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-9 Corner common to Sections 24 and 25 on East townline

Replaced pipe with $\frac{3}{4}$ " pipe and brass cap stamped Midland Co. Remon Cor. PS 29241 and is accepted as the best available evidence of the position of the original corner.

East 36.73', nail and MDOT disk in power pole
N 65 Deg W, 68.36', South corner project marker
S 62 Deg W, 138.04', NE corner store
S 62 Deg E, 59.26', pk nail in guardrail post
N 34 Deg E, 103.60', SW corner block building (old school)
North 18.57', Edenville Twp. corner A-9
(GLO jog calls for 40 links 26.4 ft.)


STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												



Signed by Rodney D. Claypool
Surveyor's Michigan License No. 29241

Date 12-28-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971

Revised Jan., 1983

APPROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

12/27/00