REMON CORNER M-11, WARREN TWP. LAND CORNER RECORDATION CERTIFICATE nt of Act 74, Mich. P.A. 1970

	Filling Requirement of Act 144 months
For comers in Midland (County)	Located in: Comer Code #
1. Public Land Survey	T 16N R 2W M-11 T R SURVEY & T R RIFMONUMENTATION
2. Property Controlling in Section	STRFE <u>B 23 2001</u>
3. Miscellaneous Property in Sec.	S T R SECTION
4. Lot No, Records 5. Private Claims	ed Plat
that under requirements of P.A. 74, lines 1 and 2 above were in confor in the current manual of survey in interior, Bureau of Land Management corner points mentioned in lines 3 of the Michigan Board of Land Sur	survey on June 23, 1999, do hereby certify Michigan P.A. of 1970, the corner points mentioned on mance with regulations and rules therefore as required estructions of the United States Department of the tent or by a decree of a Court of Law and/or that the 3,4 and 5 above were in conformance with the rules veyors or by a Decree of a Court of Law; re-established, covered, found as expressed below:
NOTE: Not more than 2 co recorded on this ce	mers, all in the same town and range, may be tificate.


548

STATE OF MICHIGAN HIDLAND COUNTY REMONUMENTATION & FILED

12/28/2000 8:44:27 AN

SCOTT I. HAINES REGISTER OF DEEDS

Register of Deeds Stamp & File Number



- A. Description of original monument and accessories and/or subsequent restoration:
- Corner common to Sections 25 and 36 on East townline M₋₁₁

Survey by Glo, 1830's, set post Survey by F. Gibbs, 1909, 1915, set ¾" steel bar Survey by MDOT, 1941, used corner Survey by M. Hunter, 1970, monument box Survey by J. Jones, 1993, found 1' rod in monument box LCRC by E. Goss, 1973, monument box LCRC by P. Lapham, 1979, monument box

- RODNEY D. CLAYFOOL LAND HVEYOR Pilm 20341 1100
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Corner common to Sections 25 and 36 on East townline

Found 3/" pipe in monument box at position per surveys by F. Gibbs, MDOT, M. Hunter, J. Jones and LCRC by E. Goss and P. Lapham.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Corner common to Sections 25 and 36 on East townline M-11

Replaced pipe with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 and is accepted as the best available evidence of the position of the original corner.

S 35 Deg E, 70.78', nail and MDOT disk in 15" Pine
N 80 Deg E, 21.65', pk nail in top guardrail post
N 25 Deg E, 74.41', chiseled "+" in East end of Southeast wingwall
N 20 Deg W, 70.90', chiseled "+" in West end of Southwest wingwall
N 50 Deg W, 64.16', nail in post
S 55 Deg W, 107.10', nail and MDOT disk in 18" Cottonwood
North 2 11', Edenville Turn corner 4-11

North 2.11', Edenville Twp. corner A-11

(GLO calls for 3 links jog 1.98 ft.)

12-26-00 Date

Signed by Surveyor's Michigan Licens No. 29241

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 Revised Jan., 1983

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY