

MAY 20 1997

RECEIVED FROM 0045

96 DEC 13 PM 3:16

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A., 1970

For corners in:

Monroe
(County)

Located In:

Corner Code #

1. Public Land Survey

Lasalle Twp.

T 7S R 8E

E-9

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Bruce Antcliff, in a field survey on July, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and / or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Monroe County Road Commission Corner

A. Description of original monument and accessories and/or subsequent restoration:

Section corner common to Sections 20, 21, 28 & 29, T7S, R8E / Stein & Suder Roads, Tarby over stone.
1820 GLO Surveyor Wampler set wood post; Hickory, 5", N85E, 16 links; Ash, 6", S75W, 6 links.
No Date, F.G. Buckley used stone.
1971, MCRC records, source unknown, RR Spike; PK Nail in power pole, N48W, 34.1';
NE Cor. of house, SW, 106.75'; PK Nail in power pole, S45W, 37.95'.
1971, Case and Fleck used RR Spike, L616, P460, same witnesses as above.
1973, Case and Fleck used RR Spike, L654, P248 and L675, P571, same witnesses as above.
1975, Community Consultants, Inc. used corner, no statement of corner type or witnesses, L692, P297.
1975, Frank Moskos, LCRC L2, P72-73, found PK Nail; NE corner 2 story frame house, SW, 106.75';
Nail in power pole, SW, 37.95'; Nail in power pole, NW, 34.10'.
1982, Marino used RR Spike for mortgage survey.
1983, Marino used RR Spike for mortgage survey.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

7/95, Found RR spike at surface, excavated 2'x2'x30" hole being about 12" below apparent original ground level. Stone road bed approx. 24" deep. Found no evidence below RR spike.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1" x 36" iron pipe with brass remonumentation cap inside monument box to replace RR Spike and is accepted as the best evidence of the position of the original corner.

Witnesses:

N38W, 34.27', PK nail in SW face of utility pole
S75 E, 174.53', PK nail in North face of utility pole
S30W, 66.37', Mag nail set in East root of 18" Oak
S50W, 38.42', PK nail in NW face of utility pole.

RATIFIED BY PEER GROUP
PA 345 OF 1990
MONROE COUNTY, MICHIGAN
date: 8/27/1996
County Rep.: [Signature]

Signed by

Bruce Antcliff

Date

11-12-96

Surveyor's Michigan License No. 25826

