

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A., 1970For corners in
MONROE (58)
(County)

Located In:

Corner Code #

WHITEFORD TWP.

T 9 S R 6 E

Miscellaneous 1

Post 52 on Michigan - Ohio Line

1. Public Land Survey

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

S T R

5. Private Claims

RECEIVED FOR RECORD
99 DEC 28 AM 8:59
REGISTER OF DEEDS
MONROE COUNTY, MICH

Register of Deeds Stamp & File Number

1999 Remonumentation Program Corner

I, George B. Warnke, Jr., in a field survey on August, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and / or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1915 - Ohio-Michigan Boundary -

From Post 51 - To Post 52, true bearing N.87°42'25"E., Distance 5024.7 feet.

Post 52 - On east side of north-south road between section 1, R5E and section 6, R6E, T6S; 0.5 mile north of Smith Siding. Post 44.0 feet south and 22.0 feet east of stone, quarter corner west side of section 6. Adjacent property east and west owned by J.A. Wilson.

(Latitude 41° 43' 23.46" Longitude 83° 45' 45.12")

To Post 53, true bearing N.87°50'42"E., Distance 5095.2 feet.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner is located by east right-of-way of County Line Road ½ mile +/- south of Yankee Road.

8/30/99 - found 8" x 10" granite post.

RATIFIED BY PEER GROUP, PA 345 OF 1990, MONROE COUNTY, MICHIGAN, DATE 10/12/1999, COUNTY REP.

Corner is accepted as a careful and faithful reestablishment of the position of the original corner as set in 1915 survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 8" x 10" granite post & Witnesses:

North 60° West 45.23 feet to set nail & remonumentation tag / shiner in southerly face of 15" Elm

North 50° West 50.83 feet to used small bolt in south face of AT&T marker pole #497

West 21.33 feet to "+" in bolt (2" sq.) in pavement

North 25° West 49.57 feet to "+" in bolt (2" sq.) at ¼ corner

North 40° East 47.15 feet to set nail & shiner in northerly face of AT&T marker pole #498

North 57 feet to ditch running east / west

about 17-1/2 feet east of centerline of pavement of County Line Road (north) & Mitchaw

Signed by

Surveyor's Michigan License No.

19474

Date October 28, 1999