

APR 28 1999

MONTCALM COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Montcalm
(County)

Located In:

Corner Code #

Day Township

1. Public Land Survey Sec T 11 N R 6 W
T 11 N R 7 W
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED

27 APR 1999 8:27:21 AM

LORI A. WILSON
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, William Tingley a field survey on October 9, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1837, John Milroy, Deputy Surveyor, GLO Notes

East corrected between Sections 19 and 30. Bearing on West Boundary.

Pine 10" N47°E 11 links

Beech 12" S11°E 27 links

1880, Henry Caukin, County Surveyor, Liber 2, Page 373, Record of Minutes of Survey

Retracing Douglass Corners.

Fire Clay Monument and blacksmith cinders

Pine Stump 18" N49°E 38 links

1896

Used again in Survey of South One-half of Section 19

No bearing tree give (40.06 chains South of West 1/4 Post)

1902, John Daoust, County Surveyor, Liber 3, Page 137

Found fireclay and new bearing tree:

Pine Stump 32" S83°E 23 links

Drove root stake by side of monuments

R.D. McNutt, County Surveyor, Index Card Records

Same data as above

1953, Michigan State Highway Department

Set 3/4" Pipe from information shown on plans 59-31 File L-28-C-1

Corner fence post S72°E 51.88 feet

Power Pole N55°E 65.28 feet

35" Oak S27°W 91.91 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron with Michigan Department of Transportation brass cap in monument box. Corner

is 2644.40 feet South of West 1/4 Corner (record 2643.96') and 2793.31 feet West of South 1/4

Corner, Section 19 (record 2793.78 feet Daoust 1907).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Standard Remonumentation Monument

Center M-66 South Sign Post S15°W 138.00 feet

Center M-66 North Sign Post N20°E 154.12 feet

Center Street-Stop Sign Post S72°W 57.85 feet

Set P.K. Nail and Tag 1 foot West of East Edge of Pavement N71°E 26.73 feet

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by William G. Tingley Date 4/16/1998

Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1976
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

ACCEPTED BY THE MONTCALM COUNTY SURVEY
GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN
PUBLIC ACT 345 OF 1990 AT A MEETING HELD 4/16/98

WGT
William Tingley, PS, Chairman

Liber 4 Page 89



370