

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
Montcalm County  
(County)

Located In:

Corner Code ##

- |                                    |   |     |   |          |      |
|------------------------------------|---|-----|---|----------|------|
| 1. Public Land Survey              | T | 12N | R | 5W       | D-10 |
|                                    | T |     | R |          |      |
|                                    | T |     | R |          |      |
|                                    | T |     | R |          |      |
| 2. Property Controlling in Section | S | 29  | T | 12N R 5W | 10   |
|                                    | S | 29  | T | 12N R 5W | 11   |
| 3. Miscellaneous Property in Sec.  | S |     | T | R        |      |
|                                    | S |     | T | R        |      |

**Register of Deeds Stamp & File Number**

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, Gary C. Bilow, in a field survey on February, 19 91, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

|    | A  | B | C  | D | E  | F | G  | H | I  | J | K  | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |   |
| 3  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 4  | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |   |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |   |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |   |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |   |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |   |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |   |

**A. Description of original monument and accessories and/or subsequent restoration:**

- D-10: Corner not established by original gov't survey. County Surveyor F.A. Palmer records in 1884 "Re-established corner originally set by S.S. Hastings who gave BT Pine 20 N1/4E 4B." County Surveyor J.F. Daoust recovered and recorded corner in 1906 writing "Found F.A. Palmer's BT of 1884 - pine stump 20 N1/4E 4B. Found stake bottom agreeing. Drove Oak stake and took NBT pine stump 36 N33-1/2E 72."
- 10: County Surveyor F.A. Palmer records in 1884 "At W1/4 1/4 post to SW 1/4 reset post set by Hastings"- no accessories given. Corner (gas pipe) established & recorded by County Surveyor J.F. Daoust in 1906 - accessories: Elm 8 N31-1/4E 24-1/2, Elm 12 S33-3/4E 44-1/2, and pine stump 30 S9E 25
- 11: Corner set by County Surveyor F.A. Palmer in 1884 - accessory: pine 22 S30E 20. County Surveyor J.F. Daoust records in 1906 "Found stake with stones around it, FAP's BT agreeing - pine stump 22 S30E 20, and drove Buggy Axle."

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

- D-10: Corner and accessories not recovered. Re-established corner at intersections of long established fence lines. Distances to corners C-10 and D-9 are reasonable and consistent with County Surveyor Records.
- 10: Found 1" iron pipe - no accessories. Found iron pipe to be 4.6' west of the section line and 1.8' north of the E-W 1/16 line. Established corner on line and equidistant between C-10 and C-11.
- 11: Did not find Buggy Axle or accessories. Found old fence post at approximate location to be 5.0' west of the N-S 1/16 line and 2.0' north of the E-W 1/16 line. Established corner at intersection of N-S and E-W 1/16 lines.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

- |  |  |  |
|--|--|--|
| D-10: Set 1/2" x 36" rebar encased in a 4" diameter concrete cylinder & capped with a cast aluminum Michigan Department of Natural Resources Tablet<br>S16E 33.16', Nail & Michigan Department of Natural Resources tag in 14" Oak<br>N71.5E 50.11', N&T in 7" Oak<br>N35E 49.71', N&T in twin 7" Cherry<br>N9W 44.03', N&T in triple 5" Oak | 10: Set 1/2" x 36" rebar encased in a 4" diameter concrete cylinder & capped with a cast aluminum Michigan Department of Natural Resources Tablet<br>N37W 25.79', N&T in 14" Oak<br>N79E 21.39', N&T in 12" Oak<br>S20E 27.40', N&T in 11" Oak<br>S35W 18.70', N&T in 7" Birch | 11: Set 1/2" x 36" rebar encased in a 4" diameter concrete cylinder & capped with a cast aluminum Michigan Department of Natural Resources Tablet<br>S60E 9.83', N&T in 12" White Pine<br>S10W 21.33', N&T in 14" Poplar<br>S70W 40.66', N&T in twin 12" 6" Oak<br>N36W 23.38', N&T in 9" White Pine |
|--|--|--|

Signed by Gary C. Bilow Date 5/22/91  
 Surveyor's Michigan License No. 26453

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN. 1983

