Cons. 4047 4/38

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_43. NR_25.W...

				Marquette	COUNT
DESCRIPTION OF	CORNER	1/4 corner	between_Se	ctions 8 and 9.	
DESCRIPTION OF	CORNER	MONUMENT	<u>l" Pipe w</u>	ith 4" Brass Ca	P•
WITNESSES TO	CORNER .	10"_Cedar_	S_36_W	4 Links	(1/4_S_HBT)
		8" Cedar	3 12 E	_39 Links	(1/4_s <u>nbt)</u>
					 -
			. -		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Tamarack B.T. bearing S 19 W_{\bullet} 19 Links. B.T. is a standing stub in excellent condition.

Corner was found by Art Enger, Assistant District Forester.

Corner was placed and witnessed on 11 August 1958 with Art Enger.

SURVEYORS SEAL

SIGNED Billy V. Buckler

DATE _5-15-59_