1993 COMMISSION TOR NUMBER: 93300 LAND CORNER RECORDATION CERTIFICATE SHEET NO. : 1-423 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in MAROUETTE Located In: Corner Code ## (County) __ R . 24W T 46N _ R ____ 1. Public Land Survey T 45N _ R Τ. _ R **Property Controlling** _ T ____ R _ _ R _ S ____ T _ in Section _ T .__ Miscellaneous Τ. Property in Sec. Lot No. . Recorded Plat 5. Private Claims _____ , in a field survey on Friday, December 24 . 19⁹³ GERALD W. CARLSON do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 13 Description of original monument and accessories and/or subsequent restoration: B-1: Quarter Corner common to Section 31, T45N-R24W and 1945 - MCRC field book 697 indicate the iron pipe and post Section 6, T45N-R24W. 1844: William Burt's original with coordinates South 9607.74 and East 12898.23 survey notes describe the corner monument as a wood post - referenced by: 4" Jack Pine \$70W 11.5 ft. referenced by: 5" Jack Pine N43E 7.1 ft. 4" Spruce Pine N25E, 19 1 1957 - Air base maps show the corner positioned in the roadway 4" Spruce Pine N28W, 15 1 with air base coordinates North 5224.14 and East 15965.23. No corner accessories given. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1993 - Corner position calculates in traveled portion of blacktop roadway. No evidence of corner exists. The position was calculated from the 1987 Donnan survey. The two Corps of Engineers brass cap irons were found and the North 1/4 corner position was calculated by extending the line between these corners and the found NE corner of Section 6 Westerly a measured distance of 658.73 ft. (659.00 ft. Recorded). A 3/4" rebar with a 3 1/4" diameter aluminum tablet were placed in a monument box in the South bound lane of Strato Fortress Street. Peer group ratification 12-20-93. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1993 - Set a 3/4" rebar capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner in a monument box in the South bound lane in the Strato Fortress Street referenced by: 76.93 ft. SE corner of building #491 N84W 70.72 ft. NW corner of building #501 N80E OF MICH NW corner of building #500 S29E 104.68 ft. NE corner of building #490 S46W 118.40 ft.

Geralda Corlser OFESSION Surveyor's Michigan License No. 🗀

Corner falls in South bound lane of Strato Fortress Street, 40 ft. +/- North of the

centerline of Invader Street.

Bk. 4, Pg. 83.

GERALD W CARLSON

SURVEYOR

No. 24589