

MAR 13 1998

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

1997 DEC 26 PM 12: 48

For corners in

MARQUETTE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 46N R 25W

L-9

T R
T R
T R
T R

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

4. Lot No. , Recorded Plat

5. Private Claims

Patricia L. Monley
REGISTER OF DEEDS

LIBER

2 PAGE 52

Register of Deeds Stamp & File Number

I, GERALD W. CARLSON, in a field survey on September 4, 19 97, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
L-9: Quarter Corner common to Sections 24 and 25.

1845: William Ives' original subdivision survey notes describe the corner monument as a wood post referenced by:

10" Maple S78E, 10 L 13" Birch N33W, 46 L

1944: Survey field notes from Marquette County Road Commission (M.C.R.C.) F.B. #712 (no pg. # given) indicate the corner as a set 1" Iron Pipe and Balsam Post referenced by:

10" Balsam N52E, 10.0' 9" Balsam S18E, 29.9'

No Date: The M.C.R.C. Government Corner Index Book (F.B. #647 - Sec. 24) indicates the corner as a 1" Iron Pipe and Balsam Post referenced by:

10" Balsam N52E, 10.0' 9" Balsam S18E, 29.9'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-9: 1997: No original corner evidence found. Found and accepted a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner and P.S. #39091. Monument is 0.2' above ground. Monument was located near the toe of a slope coursing East and South. Found five existing reference as described in Part C below. There were no nearby line calls available to check. Distance West is 2632.76' and distance East is 2626.62'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9: 1997: Found and accepted a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner and P.S. #39091. Monument is 0.2' above ground. Monument was located near the toe of a slope coursing East and South. Measured existing references:

12" Balsam Stump S18E, 30.25' (to c/l of stump) (M.C.R.C. NBT)
8" Maple N40E, 25.74' (to fd. spike)
10" Maple S35E, 54.63' (to fd. spike)
6" Maple S28W, 81.25' (to fd. spike)
9" Maple N32W, 91.75' (to fd. spike)

Established new reference:

Green Steel Sign Post w/ Yellow Survey Marker Sign N90E, 1.5'

Note: Existing bearing trees had previously painted face, butt (scribed), and side nail blazes, 1/4" dia. spikes, and B.T. Tags (not stamped) affixed.

Affixed stamped B.T. Tags

Bk. 9, Pg. 135

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

Larry J. Bussone
DATE 12/15/97

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



Signed by Gerald W. Carlson

Date 12-18-97

Surveyor's Michigan License No. 24589