

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T 46N R 28W	F5
	T	
	T	
2. Property Controlling in Section	S 16 T 46N R 28W	9
	S	
3. Miscellaneous Property in Sec.	S	
	S	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 9 09/13/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F5) Quarter corner common to Sections 9 and 16. 1982 - Reestablished and monumented by K.L.Sackett
RLS midway between Section corners east and west. Set 1"IDx32" I.pipe with 4" alum. cap. No
available witnesses. Corner falls on north bank of Black River.

(9-Sec. 16) East 1/16 corner, Section 16. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F5) Found the 1982 monument in good condition and substantially at the record position. Accepted
same as a careful and faithful reestablishment of the position of the original corner. The monument
is located 3' NE of the river's edge.

(9-Sec. 16) Established the corner midway and on a straight line between Quarter corner 1312.00' east
and Center of Section 16 1312.00' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F5) Fd. 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Balsam N20E 3.7' mrkd "1/4S NBT"
7" Balsam S37E 26.7' do
6" Balsam S28E 10.9' do
6" Balsam N25W 14.3' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
2" ID pipe gate post North 2.45'
4"x4"x5' treated wood post N47E 3.0'
Set measuring nail with MDNR tag in the side of:
6" J.Pine N34E 25.3' mrkd "1/16S BT"
6" J.Pine S31E 21.3' do
8" J.Pine S60W 25.85' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12/07/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

