

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 46N R 28W	F7
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Stephan J. Szyszkoski, in a field survey on 09/08/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F7) Quarter corner common to Sections 16 and 21. 1848 ~ Established by Harvey Mellen, Deputy Surveyor, midway and on the Section line between Section corners 39.92 chains east and west. Set Spruce post. Spruce Pine 9" S62E 14 links, Spruce Pine 9" N24W 16 links. 2000 ~ Corner reestablished and monumented by the Michigan Dept. of Natural Resources by single proportionate measurement to the original record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F7) The original post and accessories were not recovered. Found a 1"ID I.pipe with 4" alum. MDNR cap, appropriately stamped, in good condition, and at the record position, substantially midway and on the Section line between Section corners found 2636.69' west and 2636.65' east. Accepted same as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F7) Fd. 1"ID I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
10" J.Pine S47E 43.9' fd. w/old blazes and marks  
7" double Maple N40W 51.4' do  
6" J.Pine N53E 17.0' mrkd "1/4S NBT"  
5" Maple S26E 23.6' do  
Set sq'd Cedar post adjacent. Bearings are magnetic. Cap stamped with "Bressette 37270" in addition to location identification.



Signed by Stephan J. Szyszkoski Date 12/07/2010  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources and Environment, Forest Management Division