

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 28 T 46N R 30W	5
	S T R	(GCDB 340260)
	S 28 T 46N R 30W	SMC west of #5
	S T R	(GCDB 326260)
	S T R	
3. Miscellaneous Property in Sec.		
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on SMC 06/15/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 28) Center-North 1/16 corner, Section 28. Found no record of previous monumentation.

(SMC west of #5) Special Meander Corner at the intersection of the shore of Grant Lake with the
North 1/16 line of Section 28. Found no record of previous monumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 28) Established the position for the corner midway and on a straight line between Center of
Section 28 1326.71' south and Quarter corner F9 1326.71' north. From the position thus established,
I found a 1 1/4" ID I.pipe, bent, N23°W 13.9' distant, not accepted as marking the position for the
corner.

(SMC) Established the position on a straight line between monumented 1/16 corners #3 1882.32' west
and #5 736.18' east and near the east shore of Grant Lake. The position does not mark the OHWM of
the lake but is set back from the shore, in stable mineral soil. From the position thus
established, I found a 1 1/4" ID I.pipe N38°W 17.0' distant, not accepted as marking the position for
the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1" IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Maple N58°E 9.7' mrkd "1/16S BT"
7" Maple S32°E 18.95' do
12" Maple S50°W 36.4' do
14" Maple West 22.0' do
Set sq'd cedar post adjacent.
E= 7918053.968 N= 175663.053

(SMC) Set 1" IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" W.Pine N28°E 20.1' mrkd "SMC BT"
20" W.Pine S45°E 15.0' do
17" Hemlock S08°E 25.45' do
12" Maple N78°W 10.1' do
Set sq'd cedar post adjacent.
E= 7917829.636 N= 175665.649

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum
Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 08/11/2015

For the Michigan Department of Natural Resources, Forest Resources Division

