## **SURVEY &** REMONUMENTATION

JOB	NUMBER:	94030	

APR 2 & 1005

LAND CORNER RECORDATION CERTIFICATE

MARQUET	JE C	YTKUD
PECTUEN	HIGA	H
RECEIVED	FOR	RECORD

1994 DEC 28 PH 5: 54

SHEET NO.

SHEET NO. : 1-448	WI : 2 & O 1009	D		
ORBEI NO. 1 1-440		Filing Regu	irement of Act 74, Mich.	P.A. 1970
For corners in	COMMISSION			
MARQUETTE	Loca	ated In:	Corner Code ##	
(County)				1

Public Land Survey	T 47N R 25W L-13	www. Classify D
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	T R T R S T	LIBER $1$ PAGE $121$ Register of Deeds Stamp & File Number
	, Recorded Plat	A B C D E F G H I J K L M
do hereby certify that under in lines 1 and 2 above wer	, in a field survey on	red 6 18 17 16 15 14 13
Management or by a decree above were in conformance Court of Law; established expressed below:	e of a Court of Law and/or that the corner points mentioned in lines 3, 4 and with the rules of the Michigan Board of Land Surveyors or by a Decree of the re-established, monumented, re-monumented, recovered, found	d 5 8 19 20 21 22 23 24 26 as 10 30 29 28 27 26 25
NOTE: Not more than a on this certifica	4 corners, all in the same town and range, may be recorded te.	11 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Section 1, T47N-R25W. 1844: William A. Burt's original survey notes describe the corner monument as a wood post referenced by:

20" Hemlock N35E, 45 1 Hemlock N62W, 17 1

L-13: Quarter Corner common to Section 36, T48N-R25W and 1880: George P. Cummings survey indicates an iron at the corner with the following distances noted: West, 2623.501 and East, 2623.50'. No corner accessories given.

> 1910: Charles Cummings survey indicates a Corner for commencing a survey in Section 1, T47N-R25W. No corner accessories given. (See Reverse Side).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted DNR monument as referenced by G. Carlson in 1977. Distance West is 2623.41' and distance East to a calculated Township Corner in Lake Superior is 2632.61'.

RATIFIED BY PEER GROUP

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Found Department of Natural Resources iron pipe with aluminum cap in place referenced by nails in:

7" Hemlock

S62E 23.31 ft. Carlson NBT

11" Maple

8.24 ft. Carlson NBT S16W N23W 43.01 ft. Carlson NBT

15" Yellow Birch N20E 33.89 ft. Carlson NBT

Steel sign post South 1.35 ft.

Monument is stamped MCR 1994 on cap (Marquette County Remonumentation).

Bk. 5, Pg. 141

. Date ..

GERAID W CARLSON SURVEYOR No.

Gerald Warlse Surveyor's Michigan License No. \_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28,

REVISED MAY 14, 1975

## Record No. 448:

## Part "A" Continued:

1977 - G. Carlson indicates a pipe with an aluminum conservation department cap stamped to identify the corner referenced by:

(MDOT)	10" Maple,	S20W,	8.25′
	2" Maple,	N75W,	16.76′
	3" Poplar,	North,	26.55′
(Carlson)	5" Cedar,	S62E,	28.31
	10" Maple,	S16W,	8.37′
	4" Maple,	N62W,	26.53'
	P.P.,	N75E,	32.36'
	LIRC, Pg. 329		

1982 - Corner indicated on MDOT R/W map Pages 24 & 25 - no corner accessories given.