

SURVEY &
REMONUMENTATION

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1994 DEC 28 PM 5:57

JOB NUMBER: 94030

SHEET NO. : 1-498

LAND CORNER RECORDATION CERTIFICATE

APR 28 1995 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE
(County)

COMMISSION

Corner Code ##

1. Public Land Survey T 47N R 27W L-13
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Patricia L. Menley
REGISTER OF DEEDS

LIBER 1 PAGE 168
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

GERALD W. CARLSON, in a field survey on Monday, December 19, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

L-13: 1/4 Corner common to Sections 1, T46N-R27W and 3" Spruce S83W 16.2'
Section 36, T47N-R27W. 12" Pine S18W 10.2'
1846: Austin Burt's original survey notes describe the corner monument as a Cedar post referenced by:
10" White Birch N07W 21 l
7" Fir N84W 72 l
1932: M.C.R.C. field book 570 indicates the North 1/4 Corner of Section 1, T46N-R27W is a 10" squared Birch stump referenced by:
1976: Land Corner Record from C.C.I. Forest Products Division indicates the corner is a 1" drill rod referenced by:
6" Sugar Maple AZ.120 10.0'
4" Maple S89E 6.57' old bearing
13" Fir S34W 8.78' old bearing
Tag 10" White Birch 106.5' West, 9.0' North of South 1/4 Corner
248 degrees - 96.0' to pole. (See reverse side).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Corner position established equidistant and on line between the Southwest and Southeast Corners of Section 36. Distances West and East are 2637.37'. The previous position established by Brotherton was considered incorrect as the Southeast Corner of Section 36 was not considered in his survey. The re-established Southeast Corner of Section 36 (ECI double proportion - 1978) was re-calculated using the re-established Southwest Corner of Section 36 and the position would move very little. It was decided by the Marquette County Peer Group to leave the re-established Southeast Corner of Section 36 in place and re-establish the South 1/4 Corner of Section 36 as, stated above. The re-established South 1/4 Corner is S29-10'23"W, 40.77' from the Brotherton iron.

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

DATE Dec 6, 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Set a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey. Monument stamped to identify the corner referenced by nails in:
4" Twin Jack Pine S10E 35.75 ft.
5" Jack Pine S35W 19.98 ft.
4" White Pine N47W 4.57 ft.
4" White Pine N39E 9.30 ft.
Steel sign post East 1.0 ft.
Monument is 0.30' above ground. Monument is 51.5' East of two track road.
Bk. 8, Pg. 47

Signed by Gerald W. Carlson

Date 12-22-94

Surveyor's Michigan License No. 24589



2000.4.25

3300

1