## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #			
1. Public Land Survey	T 48N R 3	(GCDB 600600)			
2. Property Controlling in Section	S T R S T R S T R	(GCDB 700440)			
3. Miscellaneous Property in Sec.	S T R S T R				
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number		
above were in conformance with r instructions of the United States I a Court of Law and /or that the c	74, Michigan P.A. of 1970, the regulations and rules therefore a Department of the Interior, Burecorner points mentioned in lines 3 of Land Surveyors or by a gred, found as expressed below:	d range, may be recorded	2 4 7 8 9 10 11 12 12 13 14 13 14 13 14 13 14 15 16 15 14 15 16 15 16 16 15 16 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16		
A. Description of original monument and accessories and/or subsequent restoration:					

- (K3) Corner common to Sections 1-2-11-12. 1979 The corner was reestablished, monumented, and recorded by C.F.Clark PS 25836. See L1 of R.C., Page 350. Set 1/2"x30" capped rerod, witnessed by PK nails in: 7" Cedar N22°W 14.59', 12" W.Birch S71°E 24.93', 12" W.Birch N58°E 43.56'.
- (M6) Quarter corner common to Section 13 T48N-R30W and Section 18 T48N-R29W. 1846 Established by John Burt, Deputy Surveyor, on the Range line between Section corners 40.00 chains north and south. Set Y.Birch post. Spruce 14" S39°E 31 links, Spruce 14" N29°W 32 links. 1946 - Field Book #656 at Marquette County Rd. Commission office states: Iron pipe and cedar post set from orig. B.T.s. About 10' south of a knob of ledge about 10' high. 6" Poplar N85°E 8.6', 4" W.Birch N60°E 10.3'. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K3) The position for the corner falls on the north edge of a 2-track woods road. The 1979 monument and the 1979 Cedar NBT were not recovered. Reestablished the position for the corner at record bearing and distance from the W.Birch witnesses: the W.Birch S71°E is in good condition, the W.Birch N58°E is dead and down.
- (M6) The original post and accessories were not recovered. Found a 3/4 " I.pipe, presumed to be that noted in the 1946 record, at record bearing and distance from 2 stump mounds corresponding to the 1946 witnesses. Ledge noted in 1946 was also found about 10' north. Accepted the position of the pipe as a careful and faithful perpetuation of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap flush with the ground surface.  13" W.Birch S71°E 24.9' PK nail; single blaze Set measuring nail with MDNR tag in the side of:  5" Tamarack S16°W 24.6' mrkd "S11 NBT"  4" Maple N42°W 14.6' "S2 NBT"  9" Cedar N10°W 24.0' "S2 NBT"  Set sq'd Tam. post adjacent.  E= 7922397.065 N= 200034.387	(M6) Drove a 1"IDx28" I.pipe with 2" cap over the top of the existing 3/4' made firm in a mound of rock.  Set measuring nail with MDNR tag in 6" B.Spruce N45°E 12.3' mrkd 3" Oak S72°E 1.2' 8" Sugar S03°W 17.1' 2" Oak N18°W 16.3' E= 7923978.761 N= 197608.560	I.pipe and

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.	Datuming OF MICH
Signed by Styphen & Synpholist. Date 11/12/2014	STEPHAN J.
Surveyor's Michigan License No. 33986  For the Michigan Department of Natural Resources, Forest Resources Division	SURVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD

LAND ed Jan., 1983

Revised Oct., 1995

No. 33986