

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 16 T 48N R 30W	3
	S T R	(GCDB 300460)
	S 16 T 48N R 30W	9
	S T R	(GCDB 360440)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/28/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(3-Sec. 16) North 1/16 corner between Sections 16 and 17. Not established in the original survey.

(9-Sec. 16) Center-East 1/16 corner, Section 16. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 16) Corner not previously monumented. Established the position for the corner midway and on the Section line between Section corner 1310.82' north and Quarter corner 1310.82' south. Due to subsurface rock and roots, the monument leans to the NW and the top center of the cap is about 0.2' NW of the corner position. The witnesses below are given to the actual corner position.

(9-Sec. 16) Corner not previously monumented. Established the position for the corner midway and on a straight line between Quarter corner 1319.22' east and the Center of Section 16 1319.22' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap (see note above). Set measuring nail with MDNR tag in the side of:
4" B.Spruce S41°E 7.1' mrkd "1/16S BT"
5" Maple S06°E 13.8' do
8" B.Spruce N57°W 26.7' do
2" Maple N16°W 11.5' "X X"
Set sq'd Cedar post adjacent.
E= 7917553.827 N= 198063.482

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
4" Sugar N33°E 6.8' mrkd "1/16S BT"
10" Sugar S68°E 25.0' do
10" Sugar S35°E 18.4' do
6" Sugar S63°W 8.4' do
Set sq'd Cedar post adjacent.
E= 7918756.782 N= 197663.886

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/12/2014

For the Michigan Department of Natural Resources, Forest Resources Division

