# TO SOME SAMO CORNER RECORDATION CERTIFICATE

SHEET NO. : 1-651		rement of Act 74, Mich. P		、 胃	
For corners in  MARQUETTE (County)	Located In:	Corner Code #	07 77 m	27 M	
Public Land Survey	T <sup>48N</sup> R <sup>27W</sup> T <sup>48N</sup> R <sup>26W</sup> T R	M-6 A-6	15 No. 15	7: 4:9	25 K
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Section</li> </ol>	T R S T R S T R S T R		Register of Deeds	LIBER s Stamp 8	1 PAGE 298 A File Number
4. Lot No,	Recorded Plat		A B C	D E F	G H I J K L N

Friday, December , 19<sup>95</sup> \_, in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

### A. Description of original monument and accessories and/or subsequent restoration:

M-6: Quarter Corner common to Section 13, T48N-R27W and Section 18, T48N-R26W. 1844: Austin Burt's original survey as a found Iron in road. No accessories given. notes describe the corner as a wood post referenced by:

Sugar S43W, 34 1

14" Sugar N65W, 13 l

1992: A Certificate of Survey recorded by Larry J. Bussone placed corner in road opposite fence line South. Survey RLS #25833, in L. 002, SM Pg. 17, indicates the corner as a ties to NE and SE Corners Section 13 confirmed C/L road set 1/2" Iron Pin recorded in Marquette Co. Rec. Cor. Book. and intersection of fence line placement. Bussone set a No accessories given.

RLS #25833, in L. 002, SM Pg. 19, indicates the corner 1993: An LCRC recorded by Larry J. Bussone RLS #25833, in L. S. RC Pg. 375, indicates that Marquette Co. road data showed this corner in C/L of County Road. Local resident 1/2" Iron and Cap at this location. Established references

992: A Certificate of Survey recorded by Larry J. Bussone with upper and lower notches in trees: (See Reverse Side)

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1992: A Certificate of Survey recorded by Larry J.

1995: Found and accepted a 1/2" Iron with damaged Yellow Cap, 0.5' below gravel road at C/L. Distance North is 2628.62' and Distance South is 2625.82'.

> RATIFIED BY PEER GROUP P.A. 345 OF 1990

12/04/92



#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995: Replaced found 1/2" iron with a 3/4" X 24" rerod capped with a 3 1/4" aluminum tablet Marquette County Survey Monument, 0.53' below ground at C/L Krooks Road, and stamped to identify the corner. Measured to existing references using set duplex mails in:

18"	Maple					NOSW,	43.531	(Bussone	N.B.T.
g 11	Maple					N57E,	29.77°	(Bussone	N.B.T.
8 #	Maple					S35E,	41.90'	(Bussone	N.B.T.
10"	Maple					\$13W,	34.37"	(Bussone	N.B.T.
Gree	m Steel	Sian i	Dogt	w/Survey	Marker Sign	NIIF.	19.737		

Note: Placed blank B.T. Tag over monument to protect it. Bearing trees have face and butt blazes, paint, and B.T. Tags

Bk. 10, PP. 61-62.

Geerld W Carlson

\_\_Date\_\_12-20-95

Surveyor's Michigan License No.\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

## Record No. 651:

# Part A Continued:

11" Maple	S09W,	34.11
6" Maple	S39.5E,	41.5'
7" Maple	N51E,	29.4
16" Maple	N12W,	43.0'