REMONUMENTATION

MAY 2 2 1997

For corners in COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUE!	TE COUNTY				
MICHIGAN					
RECEIVED	FOR RECORD				

1996 DEC 20 PM 2: 13

Patricia	sd.	Mone	lece
Patrizia REGISTEI	₹ ŌF	přinas	1

RATIFIED BY PEER GROUP

P.A. 345 OF 1990

MARQUETTE (County)	Located In:	Corner Code #	Fathinad. Montey REGISTER OF PETOS O
1. Public Land Survey	T <u>48N</u> R <u>26W</u> TR TR	<u></u>	
 Property Controlling in Section Miscellaneous 	S TR S TR S TR		tirer 1 page 36
Property in Sec.	S T R		LIBER L PAGE JU Register of Deeds Stamp & File Number
i, GERALD W. CARLSON do hereby state that under req mentioned in lines 1 and 2 ab required in the current manual of Bureau of Land Management of mentioned in lines 3, 4 and 5 al	, in a field survey on OC uirements of P.A. 74, Michigan love were in conformance with resurvey instructions of the United Sor by a decree of a Court of Lapove were in conformance with the	P.A. of 1970, the corner points egulations and rules therefore as States Department of the Interior, w and/or that the corner points ne rules of the Michigan Board of	A B C D E F G H J J K L 2 - 6 - 5 - 4 - 3 - 2 - 3 4 - 7 - 8 - 9 - 10 - 11 - 1 5 - 6 - 18 - 1716 - 15 - 14 - 1 7
Land Surveyors or by a Decre recovered, found as expressed b	ee of a Court of Law; establisheelow:	ed, re-established, monumented,	8 19 20 21 22 23 2
NOTE: Not more than 2 coon on this certificate.	rners, all in the same town and	I range, may be recorded	10 30 29 28 27 26 2
A. Description of original me	onument and accessories and/o	or subsequent restoration:	12 32 33 34 35 3

No Date: The corner is shown as a Pipe on a field map of Section 34 by R.A. Brotherton DATE. for C.C.I. Co., No accessories given. No Date: The corner is shown as falling in a pond on an unidentified map of Sections 34 and 35 recorded in L. 126, Deeds Pg. 389. No

1966/1967: The corner is shown as being in a "Water Hole" on a Survey map recorded by Allen Heikkinen in L. 265, Deeds Pg. 521, and on a revised map recorded in L. 271, Deeds Pg. 393. No accessories given.

1984: A Certificate of Survey recorded by Larry J. Bussone P.S. #25833, in L. 351, Deeds Pg. 161, indicates the corner as a 1 1/2" fro Bar referenced by:

C/L Trk. S.E. Cor. Tower

accessories given.

Due West, N68W,

I-12: Quarter Corner common to Sections 34 and 35.

127.01 37.61

1845: Sam U. Hill's original subdivision survey notes describe the corner as landing in a

small lake, 563' wide, and nearly a circle in its form. No references given.

C/L P. Line Tel. Pole

Due North, N30W,

20.0 61.01

(SEE REVERSE SIDE)

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-12: 1996: Searched and no original evidence found. Found and accepted a 1 1/2" diameter from (bent) in lake. Distance West to C/L o R.R. tracks checks very well with that recorded by Larry J. Bussone P.S. #25833 in 1985. Distance North is 2650.27' and Distance South is 2652,28'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-12: 1996: Set a 3/4" X 10' long rebar at same position as found 1 1/2" Iron, and capped it with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument cap is 0.5' above water surface, and is securely wired to found 1 1/2" iron (top of which is at water level). Corner is 12' South of pole line extended from East. Referenced by:

C/L R.R. Tracks On Line with N.E. Bldg. Cor.

S87W,

127.23' (Bussone Accessory) 265.67

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

8" W. Pine

N29W, C/L Light Pole Struc. N18E,

261.511 172,391 13" W. Pine

N61W,

Green Steel Sign Post w/ Yellow Survey Marker Sign East. 2.0 Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed. Bk. 11, Pg. 151-152.

GERALD W CARLSON SURVEYOR No. 24589

Surveyor's Michigan License No


REVISED MAY 14,1975 REVISED JAN., 1983

JUL 0 3 2000

<u>l-12</u>;

PART A CONTINUED:

SECTION



1985:An LCRC recorded by Larry J. Bussone P.S. #25833, in L. 5, RC Pg. 17, indicates the corner was in Lake in Original Survey, now filled. He set a 1 1/2" Re-rod, 8' long in pond. Corner was set midway between the N.W. and S.W. Corners of Section 35. Referenced by:

C/L Trk. S.E. Cor. Tower

N68W,

Due West, 127.01 37.6'

C/L P. Line Tel. Pole

Due North, N30W,

20.0' 61.0

1993: The corner is indicated as a found iron on a Certificate of Survey recorded by Larry J. Bussone P.S. #25833, in L. 002, SM Pg. 69. Distance S89-48'-23"E, 2640.75' to the Center 1/4 Corner of Section 35. No accessories given.

1995: The corner is indicated as a Found Iron on a Certificate of Survey recorded by Larry J. Bussone P.S. #25833, in L. 402, Deeds Pg. 736. Distance S00-58'-28"E, 2650.30' to a found iron at the S.W. Comer of Section 35. No accessories given.