

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 48N R 26W

L-1

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, GERALD W. CARLSON, in a field survey on December 5 TH, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-1: North Quarter Corner of Section 1, T48N-R26W.

Corner not established during Original GLO Survey.

No subsequent record evidence recovered

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-1: 2000: SCA survey crews conducted a thorough search of the area and found no evidence of monumentation for this corner position. A 1/2" rebar was recovered as recorded by Engineering Consultants of Ishpeming, Inc. (ECI) marking the South 1/4 corner of Section 36, T49N-R26W. ECI set this monument during a survey conducted in 1982. The ECI corner position was established equidistant and on line between the SW and SE corners of Section 36. This position was based upon an erroneous position for the SW Corner of Section 36. The corner position for the North 1/4 corner of Section 1, T48N-R26W was established equidistant between the NW and NE corners of Section 1 and on line between the SE and S 1/4 corners of Section 36, T49N-R26W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-1: 2000: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.1' above ground. Referenced by:

15" Maple S60E, 13.89' 10" Maple S17E, 19.41'

10" Maple S15W, 17.99' 15" Maple N43W, 21.96'

South 1/4 Corner Section 36, T49N-R26W S89°50'55"W, 8.97'

Green Steel Sign Post w/ Yellow Survey Marker Sign South 3.0'

Distance East 2629.47', distance West 2629.47'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

Bk. 16, Pg. 55 T48N-R26W Corner Search Sheet 2000035

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

200 DEC 22 AM 10:18

Patricia L. Monberg
REGISTER OF DEEDS

LIBER **R2** PAGE 293

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

DATE

Larry J. Bussone
11/6/00



Signed by

Gerald W. Carlson

Date

12-19-00

Surveyor's Michigan License No.

24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995