Located In:

T 49N R 26W

FEB 21 2001

SECTION

MARQUETTE

(County)

Public Land Survey

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

5. Private Claims

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

L-13

MANDUETTE COUNTY
RECEIVED FOR RECORD

2000	DEC	22	ΔМ	In:	15
			m.	11.5	- 1 (

min i C
Patricia A. Manley RFGISTER OF DEEDS OF

URFR R 2 PAGE 282 Register of Deeds Stamp & File Number

> 2 3

5

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-13: South Quarter Corner of Section 36, T49N-R26W.

, Recorded Plat

1844: Austin Burt's original Township Line survey notes of T49N-R26W, describe the corner monument as a wood post referenced by:

6" Sugar

N67E, 31 links 18" Birch or Beech? M38W 05 links

P.A. 345 OF 1990

RATIFIED BY PEER GROUP

1982: ECI sketch and section breakdown indicates a set capped Rebar by single proportionate method between the found SE corner Section 36 and found GLO witnesess to the SW corner of Section 36, T49N-R26W.

1996: Certificate of Survey by ECI indicates a capped Rebar set by R.L.S. #25836, and referenced by:

6" Oak 6" Maple

S20E, West,

3.58 11.91' 8" Maple 6" Maple N40E.

4.37' S45W. 25.26

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-13: 2000: SCA survey crews conducted a thorough search of the area and found the ½" rebar as recorded by Engineering Consultants of Ishpeming, Inc. (ECI) marking the South 1/4 corner of Section 36, T49N-R26W. ECI set this monument during a survey conducted in 1982. The ECI corner position was established equidistant and on line between the SW and SE corners of Section 36. This position was based upon an erroneous position for the SW Corner of Section 36. As a result the corner position was established on the latitudinal curve by single proportionate measurement between the Southeast Corner of Section 31, T49N-R26W and the Southeast Corner of Section 36. The ECI ½" iron was 43.54' West and 7.13' South of the ratified corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-13: 2000: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.1' above ground. Referenced by:

15' Maple S71E, 22.08'

10" Maple S38E, 24.21'

10" Maple S13E, 18.20'

15" Maple N20W, 16.55'

N89°50'55"E, 8.97" North Quarter Corner Section 1, T48N-R26W Green Steel Sign Post w/ Yellow Survey Marker Sign North, 3.0'

Distance East 2638.38', distance West 2638.38'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails,

and stamped B.T. Tags affixed. Bk. 16, Pg. 57 T49N-R26W

Corner Search Sheet 2000035

TE OF WICH GERALD W CARLSON SURVEYOR No. 24520

Guell Warles