

# LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: See below

For corner(s) in: Marquette County

## Original Public Land Survey Corner

## Corner Code

a. S                      T 50N R 29W G5 (GCDB 400500)

b. S                      T 50N R 29W F5 (GCDB 340500)

S                      T            R           

S                      T            R           

## Property Corner

## 1/16 Corner Code

S                      T            R           

S                      T            R           

S                      T            R           

S                      T            R           

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

## Part A: Corner History

a.) Corner common to Sections 9-10-15-16. 1852 - Established by A.B.Wood, Deputy. Set post. Tamarack 6" N68°W 29 links, Spruce 6" S30°E 44 links. Oct. 28, 1947 - Field notes found at Mgt. Co. Rd. Commission office in Ishpeming: SE Cor. Sec. 9 50-29 in swamp. Old B.T. Spruce 6 S30°E 44 links has fallen and decayed. Scribe marks can be seen and read. Set iron pipe and spruce post. Set new BTs: Spruce 6" N23°W 3.7', Spruce 8" S40°E 27.9'. Found no subsequent record.

b.) Quarter corner common to Sections 9 and 16. 1852 - Established by A.B.Wood, Deputy. Set post midway and on the Section line between Section corners 40.04 chains east and west. Spruce 8" N48°W 6 links, W.Birch 8" S37°E 13 links. GLO line notes indicate "Leave open swamp" 1.74 chains east, and "Enter swamp" 0.51 chains west. Found no subsequent record.

## Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Mar. 30, 2017. The original post and accessories were not recovered. Found a 3/4" ID iron pipe, set firm, at record bearing and distance (note likely transposition error in the 1947 distance) from the 1947 Spruce NBT S40°E (S41°E M) 27.9' (29.7' M), which was recovered as a standing dead 12" spruce with rotting face and no markings visible. The Spruce N23°W 3.7' was not recovered. Accepted the pipe as a careful and faithful perpetuation of the position of the original corner.

b.) June 19, 2017. The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2635.32' east and west. From this position the two swamp calls noted above both check well. From the corner monumented, found a 12" cedar with flat blazes on southerly face S36°W 8.3' distant, apparently marked previously as an approximate corner position.

## Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Placed a plastic cap "MDNR PS 33986" in the top of the found 3/4" iron pipe. Set measuring nail with MDNR tag in the side of:  
 9" Tamarack N65°E 43.7' mrkd "S10 NBT"  
 6" B.Spruce S05°E 4.55' "S15 NBT"  
 3" B.Spruce S45°W 5.5' "S16 NBT"  
 4" B.Spruce N73°W 13.9' "S9 NBT"  
 Set sq'd cedar post adjacent.  
 E= 7929038.111 N= 217579.138

b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
 6" Cedar N08°E 28.5' mrkd "1/4S NBT"  
 4" Maple S53°E 11.05' do  
 12" Cedar S36°W 8.3' do  
 10" Cedar N49°W 14.3' do  
 Set sq'd cedar post adjacent.  
 E= 7928234.975 N= 217579.654

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum  
 Coord. Ref.=NGS PID RK0255: N= 219889.416 m. E= 7928749.672 m.

Stephan J. Szyszkoski

07/10/2017

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

