

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 29W	F7
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S 16 T 52N R 29W	16
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 16 11/04/2010 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F7) Quarter corner common to Sections 16-21. 1990 - G.C.Van Neste PS found an iron pipe with 3"  
brass cap with 1" I.P. adjacent, on blazed and painted N-S line, 2639.18' east of Section corner E7  
and 2636.52' west of Section corner G7.

(16-Sec. 16) East 1/16 corner between Sections 16 and 21. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F7) Found a 1"ID iron pipe with 3" brass cap, unmarked, and old 3/4"ID iron pipe adjacent.  
Monumented E7 is 2639.16' west and monumented G7 is 2636.76' east. Accepted the monument as the best  
available evidence of the position of the original corner. Found two nearby trees with overgrown  
blazes facing the monument.

(16-Sec. 16) Established the corner midway and on the Section line between Quarter corner 1318.38'  
west and Section corner 1318.38' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F7) Found 1"ID I.pipe with 3" brass cap.  
Set measuring nail with MDNR tag in the side of:  
9" Maple N03E 24.2' mrkd "1/4S NBT"  
12" Hemlock S55E 5.0' do & old marks  
13" Hemlock S84W 15.85' do do  
15" Hemlock N24W 25.0' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

(16) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
7" Sugar S56E 11.2' mrkd "1/16S BT"  
10" Hemlock S57W 23.7' do  
5" Maple N29W 2.2' do  
8" Sugar N09W 12.9' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 02/02/2011

For the Michigan Department of Natural Resources and Environment, Forest Management Division

