## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette	Located in:	Corner Code #		
(County)	8		na tit	
1. Public Land Survey	T 52N R T 52N R T R	29W C11 29W E8	e H E	
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T R S T R S T R S T R S T R		n 8:	
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number	L M
I, Stephan J. Szyszkoski, in a field survey on E8 05/03/2012 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, recovered, found as expressed below:				
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town a	and range, may be recorded	10 30 29 28 27 26 11 12 31 32 33 34 35	-36-

## A. Description of original monument and accessories and/or subsequent restoration:

(C11) Corner common to Sections 29-30-31-32. 1846 - Established by Deputy Surveyors Hubbard and Ives. Set post. Maple 12" S18E 30 links, Maple 8" N33W 16 links. 1941 - Norman T. Thompson RLS notes state that he found the Maple 12" BT S18E 30 links and described it as 'OK 22" '. He set two new BTs: Y.Birch 9" S38W 18', and Hemlock 7" S85E 17'8". He placed a Hemlock post at the corner position.

(E8) Quarter corner common to Sections 20 and 21. 1846 - Established by Deputy Surveyors Hubbard and Ives. Set post. Maple 7" S56W 26 links, Sugar 6" N63E 16 links. Undated note of Norman T. Thompson RLS: "Run this line [between 20 and 21] in 39. Cor. post both set and also 1/4 post". Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C11) The original post and accessories were not recovered. At the position for the corner, found a 1"ID I.pipe with 3.5" brass MEAD CORP. cap RLS 8317, dated 1975. An apparent NBT, 13" Hemlock with overgrown blazes and scribing was found N60W 28.5' distant. The 1941 Y.Birch NBT is a dead stub with lower blaze and scribing visible at record bearing and distance. The 1941 Hemlock NBT was not recovered. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

(E8) The original post and accessories were not recovered. The 1939 Thompson post was not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2659.94' north and south, being proportionate to the original record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C11) Found 1"ID I.pipe with 3.5" brass MEAD CORP. cap RLS 8317. Set measuring nail with MDNR tag in the side of: 3" Sugar N33E 20.8' mrkd "S29 NBT" 11" Hemlock S17E 3.15' "S32 NBT" 15" Hemlock S51W 26.5' "S31 NBT" 6" Hemlock N28W 24.3" "S30 NBT" Set sq'd Cedar post adjacent. Bearings are magnetic.

(E8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. The monument leans N'ly about 0.2'. The center of the cap marks the corner position. Set measuring nail with MDNR tag in the side of: 4" Y.Birch N85E 35.7' 14" Hemlock S65E 40.2' mrkd "1/4S NBT" do

16" Hemlock S29W 8.8' do

10" Sugar N53W 19.75' do

Set sq'd Cedar post adjacent. Bearings are magnetic.

Surveyor's Michigan License No. 33986 For the Michigan Department of Natural Resources, Forest Resources Division

STEPHAN J SZYSZKOSKI LAND JRVEYO

Date

16893 16890

Signed by

07/10/2012