

SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. of 1990 On 10/31 199 2
Mr. Davis RLS
Chairman

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T^{32N} R^{28W}

L-7

T^{_____} R^{_____}

T^{_____} R^{_____}

T^{_____} R^{_____}

2. Property Controlling
in Section

S^{_____} T^{_____} R^{_____}

S^{_____} T^{_____} R^{_____}

3. Miscellaneous
Property in Sec.

S^{_____} T^{_____} R^{_____}

S^{_____} T^{_____} R^{_____}

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	10	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, William Lenca, in a field survey on Feb. 20, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1848: Original Survey by James H. Mullett - B.T.'s - W. Pine, 15" - S05°W - 12 lks.; Hemlock, 15" - N09°E - 18 lks. No evidence of the original corner or its accessories were recovered.
- 1960: Plat of Survey by Robert Olsen, RLS No. 10700, states "Placed 1-3/4" I. Pipe painted yellow at intersection of old fence which appears to be 50 yrs or more old. Also find remains of old wood stake rotted at ground level."
- 1975: L.C.R.C. No. 87 recorded by George B. Wilson, RLS No. 17607, states "Old Iron Pipe used by R. Olsen in years past. 1-1/2" in dia." Rec'd 2" dia. iron pipe filled with concrete and stamped brass cap. NBT: 4" Maple - N10°E - 11.00'; 5" Maple - West - 17.90'; 3" Oak - N10°W - 7.70'.
- 1982: CERTIFIED SURVEY No. 295 recorded by George B. Wilson, RLS No. 17607, shows this corner as it relates to other corners in Section 13.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 2 inch diameter iron pipe with a 2-1/4 inch diameter brass cap stamped for corner location, along with the 3 B.T.'s as described in L.C.R.C. No. 87 (see part "A"). This corner has been accepted and used by local surveyors for at least 37 years, and is accepted as the best available evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 2" dia. Iron Pipe/2-12" Brass Cap stamped for corner location:

5" dia. White Ash	N73°W	37.90 feet	Scr. NBT
6" dia. Maple	S32°W	16.53 feet	Scr. NBT
9" dia. Maple	East	5.60 feet	Scr. NBT
12" dia. White Ash	N28°E	25.80 feet	Scr. NBT
Metal Survey Sign Post	N50°W	3.7 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date Apr. 10, 1997

Surveyor's Michigan License No. 26461

