

SURVEY & REMONUMENTATION

JAN 09 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12/22, 2000
McMAHON RLS
Chairman

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 33N R 26W

F-9

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca, in a field survey on Nov., 19 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Cedar, 14" - S52°E - 10 lks.; Hemlock, 24" - N22°W - 6 lks.; All original evidence for this corner has been destroyed by County Road improvements.
- 1986: L.C.R.C. No. 742, Book 3, by William Lenca, RLS No. 26461 states "found 1/2" dia. Iron Pin in center of East-West county road in line with ancient fence to the South". TIES: Power Pole, S63°E, 64.35'; Maple, 8", S45°W, 49.32'; White Birch, 10", N20°W, 31.78'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1/2" diameter Iron Pin in the centerline of an East-West county road and in line with an ancient fence running South per L.C.R.C. No. 742 (see part A above). This corner position fits well with measurements to other corners in the area, has been accepted and used by local surveyors for many years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location:

10" dia. Maple

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"

9" dia. Maple (Existing B.T.)

12" dia. White Birch (Existing B.T.)

Metal Survey Sign Post

N60°E

39.77 feet

Scr. N.B.T.

S56°E

65.08 feet

1.0' S. of PP

S45°W

49.32 feet

Scr. N.B.T.

N20°W

31.78 feet

Scr. N.B.T.

South

33.2 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date Dec. 20, 2000

Surveyor's Michigan License No. 26461

