
Approved by Menominee County Land Survey Remonumentation LAND CORNER RECORDATION CERTIFICATE Peer Group Under Act 345 Of Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Corner Code # Located In: MENOMINEE D05 T33N R 27W 1. Public Land Survey 2. Property Controlling . in Section Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. _, Recorded Plat_ 5. Private Claims I, <u>William Londa</u>, in a field survey on <u>Fch 08</u>, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the 5

Composition to the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and Journal of Court that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
 - Original Survey by John Mullett B.T.'s Cedar, 10" S42°W 08 lks, Cedar, 8" N13°W 13 lks. All original
 - Certified Survey No. 223, recorded by George B. Wilson, RLS No. 17607, shows this corner as it relates to other corners in 1981:
 - Section 8, T33N-R27W. The corner monument is not described and no B.T.'s are given. L.C.R.C. No. 372, Book 2 recorded by George B. Wilson, RLS No. 17607, states "Found iron pin, used in old surveys." Set HDR Monument at Corner - WITNESSES: Deep 1 - 5 feet South; Deep 1 - 5 feet East. 1982:
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

We found a 3/4" diameter aluminum rod with a 3-1/4 inch diameter aluminum cap (known as a Berntsen HDR Monument) 43 feet south of the centerline of an existing East - West county road, and in line with old fence lines running North and South from this location. This corner position also matches with that shown in Certified Survey No. 223. This corner has been used by local surveyors for many years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Accepted existing 3/4" dia. alum. rod/3-1/4" dia. alum. cap stamped for corner location:

Scr. NBT 76.85 feet $N00^{0}E$ 12" dia, Elm Scr. NBT \$550E 5.18 feet 11" dia. Hemlock Scr. NBT 21.52 feet S630W 12" dia. White Ash 1.0 feet South Metal Survey Sign Post



NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

10) Minu Fred Surveyor's Michigan License No.

Nov. 20, 1996 Date .

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1 REVISED MAY 14,1 REVISED JAN., 1 REVISED OCT., 1