Approved by Menominee County Land Survey Remonumentation

Peer Group Under Act 345 Of P.A. Of 1990 On LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 WOLL STATES HERE For corners in Corner Code ## Located In: MENOMINEE K-1 Public Land Survey R R R **Property Controlling** S T R in Section Register of Deeds Stamp & File Number R S Miscellaneous Property in Sec. R , Recorded Plat Lot No. Private Claims (SAME AS CORNER K-13 T34N - R27W) Apr. 13 in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Vanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Sourt of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original Survey (Twp Boundary) by James H. Mullett - B.T.'s - Hemlock, 12"- N21°W - 17 lks; Lynn, (no size) N73°E -45 lks. All original evidence for this corner has been destroyed by county road improvements. Original Survey (Sec. Subdivision) by John H. Mullett - B.T.'s - Hemlock, 12"--S62°E - 17 lks; Hemlock, 13" - S58°W -1848: 11 lks. All original evidence for this corner has been destroyed by county road improvements. Certified Survey No. 215 by William Lenca, RLS No. 26461, shows this corner in relation to other corners in Section 35, 1981: T34N-R27W. The survey legend indicates a 1/2" dia, iron was found. No corner ties are shown. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We found a 4 inch square concrete monument with a 1/2 inch diameter iron rod in the center in a location matching measurements to corners North and West of the location. The corner is in line with the centerline of county roads North and West and in line with an ancient sence running South. We accepted the position of the concrete monument as the best available evidence of the position of the original corner. Description of monument for corner and accessories established to perpetuate locating the position of the corner Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location: WILLIAM LENCA N420E 5/8" x 24" Iron Rod/2" cap marked WITNESS MARKER 45.30 fcct 5/8" x 24" Iron Rod/2" cap marked WITNESS MARKER S490E 27,16 feet SIIOW 118.92 fcct 5/8" x 24" Iron Rod/2" cap marked WITNESS MARKER 5/8" x 24" Iron Rod/2" cap marked WITNESS MARKER N53°W 76.61 fcct 23.1 feet RED LAND South Metal Survey Sign Post NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Oct. 20, 1995 William Inda Date . FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 26461 Jurveyor's Michigan License No. 2