

Filing Requirement of Act 74, Mich. P.A. 1970

MENOMINEE

(COUNTY) COMMISSIONERS

Located In:

Corner Code ~~==~~

- | | | | | | |
|------------------------------------|---|-------------|---|-------------|-------------|
| 1. Public Land Survey | T | <u>33</u> N | R | <u>27</u> W | <u>K-10</u> |
| | T | _____ | R | _____ | _____ |
| | T | _____ | R | _____ | _____ |
| | T | _____ | R | _____ | _____ |
| 2. Property Controlling in Section | S | _____ | T | _____ | _____ |
| | S | _____ | T | _____ | _____ |
| 3. Miscellaneous Property in Sec. | S | _____ | T | _____ | _____ |
| | S | _____ | T | _____ | _____ |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

William Lenca

Oct. 06

94

I, _____, in a field survey on _____, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

[illegible]

- A. Description of original monument and accessories and/or subsequent restoration:**

- 1848: Original Survey by John Mullett - B.T.'s - Tamarack, 7" - S21°E - 06 lks; Tamarack, 5" - N53°W - 10 lks. No original evidence for this corner was recovered.
- 1990: Survey and subdivision of Section 25, T33N-R27W by William Lenca, RLS 26461 - notes state that a 5/8" dia. x 24" iron rod/ident. cap was set in location of an old squared wood post. New B.T.'s: 5" dia. Tam - N02°W - 35.50 feet; 4" dia. Tam, - S87°E - 28.54 feet; 5" dia. Tam, - S11°W - 14.35 feet; 6" dia. Maple, - N77°W - 16.56 feet.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered the 5/8" dia. x 24" iron rod at an old squared wood post, and 4 B.T.'s as described in part "A". An old fence runs East from this location. This corner position has been accepted and used for many years, and is accepted as the best available evidence of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2-1/2" Alum. Pipe 30" long/3-1/4" dia. Aluminum cap stamped for corner location:

5" dia. Tamarack (Ex. B.T.)	N02°W	35.50 feet	Scr. NBT
4" dia. Tamarack (Ex. B.T.)	S87°E	28.54 feet	Scr. NBT
5" dia. Tamarack (Ex. B.T.)	S11°W	14.35 feet	Scr. NBT
6" dia. Maple (Ex. B.T.)	N77°W	16.56 feet	Scr. NBT
Survey Sign Post	N90°W	1.5 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William F. Zuck Date _____

Nov. 29, 1994

Surveyor's Michigan License No. 26461

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

135