APR 06 1999

				P.A. Of 1990	On	<u></u>
SECT	ON LAND	CORNER RECORDATION	ON CERTIFICA	ATE	Mes on	WIS RLS
For corners in	Filing	Requirement of Act 74,	Mich. P.A. 197	70	Chairman	
MENOMINEE *					Marker C	စ္က 😤
(County)	Located In:	Corner Code #			OND A	RECEIVED FOR RECORD
					第128名	
Public Land Survey	T <u>35N</u> R_ 2 T R	28W 1-10			국육성 >	n s
	<u>'R</u>		ļ		に記える	
0 December 0 - 111	TR_				3850 A 6	<b>ў</b>
Property Controlling     in Section	S   R S T R				@S	71 <del>-</del>
3. Miscellaneous	S TR					
Property in Sec.	S TR			Register o	of Deeds Stam	p & File Number
				11310101	TOOGO CAM	p a r ile Hamber
4. Lot No, Record	ded Plat		·		) F F &	
5. Private Claims						
•				2 6	5 4 4	3
William Lenca	in a field survey on	Sept. 17 19 98 do hereby	state that under	3 4 7 - 1		
I, William Lenca, requirements of P.A. 74, Michigar conformance with regulations and	n P.A. of 1970, the corner prules therefore as required in	points mentioned in lines 1 and	2 above were in	5		
United States Department of the in	nterior. Bureau of Land Man	agement or by a decree of a Cou	rt of I aw and for	6 -18 -1	716	15-1-13
that the corner points mentioned i Board of Land Surveyors or by	a Decree of a Court of L	re in conformance with the rules .aw; established, re-established	of the Michigan  , monumented.	7		
recovered, found as expressed belo	ow:	·		8 -19 -2	0 21 2	222324-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				9		
on this certificate.				10 30 2	9282	27-49-2625-
				11		
,				12 31 31	2 33 3	34 35 36
A. Description of original mon	nument and accessories	and/or subsequent restorati	on:			· · · · · · · · · · · · · · · · · · ·
1852: Original Survey t evidence for this	corner has been destroy	3.T.'s - W. Birch, 14" - N40 yed by county road improve	ements.	7. Pine, 14 - 1	543°E - 60 183	s. An original
B. Description of corner evide	ence found and/or metho	od applied in restoring or ree	stablishing corne	r.		
We set this corner at the ir measurements to corners 1 original corner.						
					ald	promote services
		•			A TATE	100
						WILLIAM +
						LAND
						SIJEVEYOR No.
C. Description of monument fo	or corner and accessorie	s established to perpetuate I	ocating the positi	on of the corne	er:	35461
Set 2" dia. Aluminum Pipe	e 30" long/3-1/4" dia. <i>A</i>	Alum. cap stamped for corr	ner location:		ADDITE.	AEO LETO
5/8" x 24" Iron Rod/2"	dia. Alum. cap market	d "WITNESS MARKER" 8" dia. White Ash 9" dia. White Ash 12" dia. Cedar Metal Survey Sign Post	S55°E 6 S51°W 8 N37°W 7	2.42 feet	I'N. of Rd. Si "X" cut in upp blazes of B.T.	er and lower
NOTE: All bearings are n	nagnetic bearings. All		th steel tape. Di	stances to tree	s are to nail i	n side of tree.
Signed by William	Luis -		Date De	c. 18, 1998		
Surveyor's Michigan License No	)			<del></del>		
	20461	· · · · · · · · · · · · · · · · · · ·				