REMONUMENTATION

APR 2 4 1995

LAND CORNER RECORDATION CERTIFICATE

Poer Group Under Act 345 Of
PAG 1880 0 12/9 10 94
Me DAVI RLS
ALTERIA :

LENCA SLIBVEYOR

Approved by Menominee County Land Survey Remonumentation

on this certificate.

Fo	COMMISS or corners in	ION Filing Requ	uirement of Act 74, Mi	ch. P.A. 1970	0 7	ICTING	6				
	MENOMINEE (County)	Located In:	Corner Code =##				15 Se 1) 	RF.		
1.	Public Land Survey	T 36N R 28W T R T R T B		_		BARA MOR BISTER OF D BISTER OF D	#100 B光 #1117 開	ָ ק	SFOYIVED FOR R		\$ 13 14 14
2. 3.	in Section Miscellaneous	S T R S T R S T R		_	egister of D	े हिंदी अपने Geeds Sta	ت م	p §	RESE	er	
	Property in Sec.		•	·····		· · · · · · · · · · · · · · · · · · ·					
4 . 5 .		Recorded Plat			- A B - 2 - 6 - 3	C D E	F G	# !	J 1	K L	<u>, , , , , , , , , , , , , , , , , , , </u>
I	William Lenca	, in a field survey on	June 14, 19	94	4 - 7-	-	·	10	_ _	-	
in cu Ma ab Co	hereby certify that under re lines 1 and 2 above were crent manual of survey instrangement or by a decree of ove were in conformance w	equirements of P.A. 74, Michigan P in conformance with regulations ructions of the United States Dep I a Court of Law and/or that the co rith the rules of the Michigan Boar re-established, monumented, r	P.A. of 1970, the corner points and rules therefore as requestment of the Interior, Bur more points mentioned in line and of Land Surveyors or by a	s mentioned uired in the eau of Land es 3, 4 and 5 Decree of a	6 18-7 8 19- 9 10 30-	20	21	22	23-		3-
NI/	TE. Not more than 4	corners, all in the same town	and range, may be reco	orded	11	⋠ ╌╌ ├	+			┿	

Description of original monument and accessories and/or subsequent restoration:

Original Survey by H. Brevoort - B.T.'s - W. Pine, 20", N32°W, 30 lks & Aspen, 14", S29°W, 50 lks. All original evidence for this corner has been destroyed by County Road improvements.

L.C.R.C. No. 221 recorded by David Babbitt, RLS No. 21558, states that a 1" dia. Iron Pipe/4" aluminum cap was set on 1979: line between the W1/4 Cor. of Sec. 19 & the W1/4 Cor. of Sec. 30 & in the center of an E-W County Road. B.T.'s - 6"

Twin Red Pine - N01°E - 54.5'; Power Pole - N70°E - 87.6'; 9" Cedar - S61°E - 139.3'; 4" W. Birch - S61°W - 52.4'.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The Corner Monument described in LCRC No. 221 (mentioned in part "A") has been destroyed by county road improvements. A DNR Retracement Survey Map dated 1980 shows the relation of this corner position to the W1/4 Corner of Section 25 and the W1/4 Corner of Section 24 of T36N-R28W. We traversed between these corners and placed the corner position accordingly. We also found the B.T.'s mentioned in part "A" and found that they fit this position. We accepted this corner as a careful and faithful re-TO TO THE PARTY OF establishment of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location:

5/8" x 24" Iron Rod/2" alum. cap	N75°E	86.45 feet	
10" dia. Cedar	S51°E	139.42 feet	Scr. NBT
6" dia. W. Birch	S67°W	52.45 feet	Scr. NBT
12" dia. Twin Red Pine	NO5°E	55.10 feet	Scr. NBT
Survey Sign Post	N03°E	28.6 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Janea Date	Sep. 14, 1994
Surveyor's Michigan License No26461	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19