## REMONUMENTATION

APR 2 4 1995	LAND COR	LAND CORNER RECORDATION CERTIFICATE		PACING DEC 16 m 4		
COLORISCION		irement of Act 74, M	•		April BLS	
For corners GOMMISSION	•			ACTING"	77)	
MENOMINEE	Located In:	Corner Code ##		只是近年	RECEIVED FOR 4 DEC 27	
(County)		, , , , , , , , , , , , , , , , , , , ,		200		
4 Dublis Land Commission	<b>.</b>				6 2 B	
Public Land Survey	T37N R26V					
	<u>T</u> <u>B</u>			35 70°	- <del>2</del>	
	ŢR		-			
	Ţ Ŗ	<del></del>	— i	985 C	NECORO NI IO: U	
	<u>T</u> <u>R</u>		l'	င္လိုက္ခင္	£ 65	
	<u>T</u> <u>R</u>		*****	d.,		
	T R		— Regi	ister of Deeds St	amp & File Number	
Property in Sec. S	T R					
4						
4. Lot No, Records				ABCDE	F G H 11 J K L	
5. Private Claims		<del></del>	<del></del>			
				2 - 6 - 5	- 432	
				3	<del></del>	
William Lenca		Jun 22	94	4	- 9 - 10 - 11 - 1	
	letd survey on		·	5	╼┼┼┼┼	
do hereby certify that under requirement in lines 1 and 2 above were in confor	ntsorP.A. 74, Michigan P./	A. 01 1970, the corner points and rules therefore as rea	smentioned	6 18 17	-161514	
current manual of survey instructions				7		
Management or by a decree of a Court o	of Law and/or that the corr	erpoints mentioned in line	es 3, 4 and 5	8 19 30		
above were in conformance with the ru				9	-21 -22 -23	
Court of Law; established, re-estable	ished, monumented, re	-monumented, recovered	l, found as			
expressed below:				10 30 29	-28 -27 -26 -2	
NOTE: Not more than 4 corners,	all in the same town a	and range, may be reco	orded	11	<del></del>	
on this certificate.				12 31 32	-333435	
,				13		
A. Description of original monum	ent and accessories ar	nd/or subsequent resto	ration:		•	
1852: Original Survey by F	rancis Coleman - B.T.	- Cedar, 14"- N24°E -	48 lks; Maple -	16", S580W - 18 I	ks - All original	
evidence for this corn	er has been destroyed b	y county road improvem	ents.	•	· ·	
-					•	
1982: L.C.R.C. No. 542 reco	orded by William Lenca	a, RLS No. 26461, states	s that a 3/4" x 18'	" Iron Pipe was pl	aced by single	
proportionate measure	ement - B.T.'s - 5" W. I	Birch - N40 <sup>o</sup> W - 59.72';	20" Cedar - N63	°E - 17.27'.		
				•		
•				0		
. Description of corner evidence	found and/or mathod	annlied in restoring or	ropetablishing c	ornar		
. Description of comer evidence	Tourid and/or metriod	applied in restoring or	reestablishing e	omer.	•	
Found 3/4" x 18" Iron Pipe and	I B.T.'s mentioned in p	art "A". This corner wa	s established by s	single proportiona	ite measurement in a	
1982 survey of Section 16. Th	e corner position falls i	n line with the centerlin	e of a county road	d running West ar	nd South from this	
location, and is accepted as a c	areful and faithful re-es	tablishment of the posit	ion of the origina	al corner.		
		-		~~	mman	
				WILL O	MICHION	
				attle 14	14 E	
	•	•		∦ ★ · Wi	LLIAM : * B	
				13	NCA +	
				N . ! -	RVEYOR *	
					No.	
					16461	
				Barris.	CURY TEL	
•				ASSOCIATION ALL	LANU	
* Description of monument for or	orner and accessories	established to nemetur	ate locating the	position of the co	orner:	

Set 2-1/2" dia. alum. pipe 30" long/3-1/4" dia. Alum. cap stamped for corner location:

22" dia. Cedar (Ex. B.T.)	N63 <sup>0</sup> E	17.27 feet	Scr. NBT
6" dia. Cedar	S31°E	12.57 feet	Scr. NBT
6" dia. Cedar	S77°W	110.59 feet	Scr. NBT
8" dia. White Birch (Ex. B.T.)	N40 <sup>0</sup> W	59.72 feet	Scr. NBT
Survey Sign Post	S74°E	1.7 feet	•

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Frace De	ate <u>Sep. 15, 1994</u>
Surveyor's Michigan License No	CODE ARRONDO DE MICHICALI STATE BOLDO DE LAND SHEWEYDES JAN 28 197