

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Montmorency  
(County)

Located In

1. Public Land Survey T R  
T R  
2. Property Controlling in Section S 30 T 29N R 3E 3  
S 30 T 29N R 3E 10  
3. Miscellaneous Property in Section S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on September 27, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

3 – N1/16 Cor. Common to section 30, T29N,R03E and section 25, T29N,R02E 10 – S1/16 Cor. Common to section 30, T29N,R03E and section 25, T29N,R02E

1975 Kenneth J. Ostling P.S. #10068 set 1" pipe for corner

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

3 – N1/16 Cor. Common to section 30, T29N,R03E and section 25, T29N,R02E 10 – S1/16 Cor. Common to section 30, T29N,R03E and section 25, T29N,R02E

Found 1/2" x 36" rod with illegible P.S. cap fitting the Standard BLM Procedure for the subdivision of a section.  
Removed 1/2" x 36" rod and added 5/8" x 34" rerod with 2" Aluminum cap.

Found a well point fitting the Standard BLM Procedure for The subdivision of a section.  
Also found a 1" pipe set in error by K.J. Ostling 4.97' South

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3 – N1/16 Cor. Common to section 30, T29N,R03E and section 25, T29N,R02E 10 – S1/16 Cor. Common to section 30, T29N,R03E and section 25, T29N,R02E

Stamped 2" aluminum cap on 5/8" x 34" rebar

Drove a 5/8" rerod with 2" aluminum cap in found well point

Wits: N42°E 13.25' to set N&T NW side 3" Oak  
S51°E 16.26' to set N&T N side 30" Cedar  
S37°W 13.96' to set N&T SE side 6" Balsam  
N47°W 31.92' to set N&T SW side 12" R. Maple  
Set BCP 1' North

Wits: N33°E 5.87' to set N&T W side 3" & 5" twin Balsam Fir  
S62°E 15.20' to set N&T S side 7" Oak  
N89°W 1.08' to set N&T S side 4" Balsam Fir  
N16°W 21.70' to set N&T W side 4" Balsam Fir  
S2°W 4.97' to found 1" pipe set by K.J. Ostling  
Center N-S road East 135' set BCP North 1'

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981



12-20-10