

SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0446

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MONTMORENCY
(County)

Located in:
BRILEY TWP.

Corner Code #

1. Public Land Survey

T 30N R 2E G-2

T R

T R

T R

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

S T R

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

12-05-2000 10:07:21

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6		5			4	●	3		2		1
3												
4	7		8			9		10		11		12
5												
6	18		17			16		15		14		13
7												
8	19		20			21		22		23		24
9												
10	30		29			28		27		26		25
11												
12	31		32			33		34		35		36
13												

I, DONALD E MARLATT, in a field survey on MAY 2000, 16X do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-2 1/4 CORNER COMMON TO SECTIONS 3 & 4.

G.L.O. COR. SET BY LEWIS CLASON IN APR. 1840. ASPEN 7" N48°W 10 L., ASPEN 9" S29°E 8 L. COUNTY ROAD COMMISSION NOTES: NO DATE OR DESCRIPTION OF CORNER. S 5°W 30.5' 11"TW. MAPLE, S30°W 50' 6"TW. MAPLE, S55°W 70' 5"CEDAR.

D.E. MARLATT P.S. #18660 ACT 132 DATED 10/12/77. FOUND 1 1/4"PIPE. S10°W 12"TW. MAPLE 29.70', S45°W 8"CEDAR 30.20', NORTH 24.25' CORNER FENCE POST.

D.E. MARLATT P.S. ACT 132 DATED 5/14/79. FOUND 1 1/4' PIPE. S14°W 30.4' 14"TW. MAPLE, S40°W 50.1' 8"MAPLE, NORTH 33' 1/2"ROD.

D.E. MARLATT P.S. ACT 132 DATED 5/19/79. FOUND 1 1/4"PIPE(WIT. SAME AS ABOVE.

D.E. MARLATT P.S. ACT 132 DATED 5/8/90. FOUND 1 1/4"PIPE. S10°W 12"TW. MAPLE 29.7', S45°W 8"CEDAR 30.2', NORTH FENCE POST 24.25'.

D.E. MARLATT P.S. ACT 132 DATED 12/16/99. FOUND 1 1/4"WELL PIPE & REPLACED WITH CONC. MONUMENT. N30°W 10"CEDAR 58.57', S45°W 8"TW. MAPLE 50.2', S20°W 12"TW MAPLE 30.43', S77°W 12"CEDAR 60.9'

B. Description of cor. evidence found and/or method applied in restoring or reestablishing cor.

G-2 1/4 CORNER COMMON TO SECTIONS 3 & 4.

FOUND CONC. MONUMENT

N30°E 10"CEDAR 58.57'R.

S45°W 8"TW. MAPLE 50.20'R.

S20°W 12"TW. MAPLE 30.43'R.

S77°W 12"CEDAR 60.96' R.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-2 1/4 CORNER COMMON TO SECTIONS 3 & 4.

PLACED REMON. CAP ON EXISTING CONC. MONUMENT.

N30°E 10"CEDAR 58.57'

S45°W 8"TW. MAPLE 50.20'


S20°W 12"TW. MAPLE 30.43'

S77°W 12"CEDAR 60.96'

APPROVED BY
PEER GROUP

12 18 00

L.Y.B.



WITNESSES MARKED WITH 40 PENNY SPIKES AND P.S. TAGS #18660.

APPROVED BY PEER GROUP ON JULY 18, 2000 AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Donald E Marlatt
Surveyor's Michigan License No. 18660

Date 12/4/2000