

MAY 16 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>MONTMORENCY</u> (County)	Located In:	Corner Code ##
<u>HILLMAN TWP.</u>		
1. Public Land Survey	T <u>31N</u> R <u>4E</u>	<u>F - 13</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-01-1996 09:42:27

A. PANGAN-MCELROY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, DONALD E MARLATT, in a field survey on JULY 1, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F - 13 SOUTH 1/4 COR. OF SEC. 33
COR. SET BY LEWIS CLASON 3-18-1839
CEDAR 6"-N22°W-10, ASPEN 6"-N35°E-12
ACT 74 BY D. PORTER L. 1, P. 80, 1-4-1974. FOUND 1/2" ROD & CAP
S70°W 14.32' FE. POST
SOUTH 51.0' FE. POST
S70°E 13.81' FE. POST

SURVEY BY D. PORTER L. 3, P. 151, 10-8-1981

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F - 13 SOUTH 1/4 CORNER OF SEC. 33, T31N, R4E.
FOUND 1/2 " ROD AND CAP#15410 (NO WIT. NEW FENCE LINE)

**APPROVED BY
PEER GROUP**

JUL 12 96

L.D.B.

NORTH CORNER COMMON TO SEC'S 3 & 4 IS 81.1' WEST

NO EVIDENCE OF ORIGINAL CORNER

NOTE: MSHD SURVEY DATED 4-5-1966 WAS NOT ACCEPTED FOR CORNER POSITION.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F - 13 SOUTH 1/4 CORNER OF SEC. 33, T31N, R4E.
SET CONC. MONUMENT WITH REMON. CAP.
S15°W FE. POST 4.45'
S65°E FE. POST 15.44'
S79°W FE. POST 16.4'
S88°W FE. POST 31.46'

WITNESSES MARKED WITH 30 PENNY SPIKES AND P.S. TAGS#18660
APPROVED BY PEER GROUP JULY 12, 1996 AS THE BEST AVAILABLE EVIDENCE OF
THE POSITION OF THE ORIGINAL CORNER.



d by Donald E Marlatt
Surveyor's Michigan License No. 18660

Date 10/20/96