

LIBER 17932 PG 778

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

(County)

Located In: Farmington Twp. Corner Code #

1. Public Land Survey

T 1-N R 9-E

E-8

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

SURVEY &  
REMONUMENTATION

MAR 21 2000

SECTION

\$ 7.00 MISCELLANEOUS RECORDING

\$ 2.00 REMONUMENTATION

2 JAN 98 9:03 A.M. RECEIPT# 12A

PAID

RECORDED - OAKLAND COUNTY

LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

ACT 345, P.A. 1990

APPROVED ON: 4-28-97 TS

OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

Register of Deeds Stamp &amp; File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, John N. Redash, in a field survey on March 6, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		16		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

A. Description of original monument and accessories and/or subsequent restoration:

1817 Set post

S. Carpenter

n/a

GLO notes

1977 Found 1/2" iron in monument box

D. Vitins

#17324

L.C.R.C. L6889, P407

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A found pipe in monument box currently occupies this corner. The following witness ties were used to recover and verify its position: Three current measurements match ties on L.C.R.C. L6889, P407, 408

Field measurements were made between the following corners:

E-8 to E-7

2643.98 meas.

2640.00 Rec. G., L.O.

2644.04 Rec. Plate L160, P27

E-8 to E-9

2652.80 meas.

2640.00 G.L.O.

2650.19 Tax maps (20-F)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the found pipe with a 5/8" x 24" iron rod with 2" diameter brass cap stamped "Oakland County Remonumentation PS#37281". Witnesses as follows:

N. 30° E.,	206.58'	Centerline top nut fire hydrant
N. 60° E.,	148.58'	P.K. nail and remon. washer S.E. face U-pole
S. 30° W.,	158.61'	P.K. nail and remon. washer E. face U-pole
S. 80° W.,	58.02'	P.K. nail and remon. washer S. face U-pole
S. 35° E.,	165.70'	Centerline sanitary manhole



The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by

Date April 24, 1997

Surveyor's Michigan License No. 37281