LIBER 18319PC 433

LAND CORNER RECORDATION CERTIFICATE

For corners in Filing Requirement of Act 74, Mich. P.A. 1970			
Oakland (County)	Located In: Corner Code # West Bloomfield Township	\$ 2.00	HISCELLANEOUS RECORDING C REMONMENTATION 98 1:43 P.M. RECEIPT# 1066-
1. Public Land Survey	T <u>2N</u> R <u>9E G-2</u> T R T R	PAID	98 1:43 P.N. RECEIPT# 1062 RECORDED - DAKLAND COUNTY ALLEN, CLERK/REGISTER OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec. 	S_ T_ R S_ T_ R S_ T_ R	1	Compliance with ACT 345, P.A. 1990 OVED ON: 3-4-58 JS AND COUNTY REMONUMENTATIO PEER GROUP COMMITTEE
4. Lot No, Record 5. Private Claims	ed Plat SECTION We	Sloon Feet	ister of Deeds Stamo & File Numi
		2 - 6 - 3	DEFGHIJKL
conformance with regulations and rule United States Department of the Inter- that the corner points mentioned in lin	a field survey on <u>January 19</u> , 19 <u>98</u> o hereby A. of 1970, the corner points mentioned in lines 1 and is therefore as required in the current manual of survey or, Bureau of Land Management or by a decree of a C es 3, 4 and 5 above were in conformance with the rule Decree of a Court of Law; established, re-establish	I 2 above were in instructions of the built of Law and/or is of the Michigan and, monumented, 7	-17 -16 -15 -14 -13 - -20 -21 -22 -23 -24
on this certificate.	s, all in the same town and range, may be record	10 30	-29 - 28 - 27 - 26 - 25 -
1817-GLO Carpenter, D.S.; Set Post 40" White Oak N20 % E 89 Links; 5" Hickory N78"W 37 ½ Links 1.) 1992-Bishop, PS #25829; LCRC L.12309, Pg.187 - Fnd 1" Pipe 2.) 1992-Fraus, PS #17089; LCRC L.12477, Pg.478 - Fnd ½" Pipe 3.) 1993-Kapelczak, PS #24598; LCRC L.13600, Pg.211 - Fnd 1" Pipe 4.) 1994-Platz, PS #38121; LCRC L.15176, Pg.205 - Fnd ½" Iron 5.) 1988-Kapelczak, PS #24598; Unrecorded Survey, object found not stated, no witnesses 6.) 1992-JCK & Associates, Inc; Unrecorded Survey - Fnd 1" Pipe, used same wit as first LCRC B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1998-Kennedy Surveying, Inc Kennedy, PS #17623 - ½" Iron Rod Inside a ¾" Iron Pipe 8.70 feet North of the existing centerline of Greer Road extending to the East & West, which has a bituminous surface. A tree line extending to the South. Witnesses from LCRC #2,& 4 were used to recover and verify the location of the found ½" Iron Rod inside a ¾" Iron Pipe.			
I accepted the found ½" Iron Rod inside a ¾" Iron Pipe as the best evidence of the original corner positon. FIELD MEASURMENTS BETWEEN			
G-2 to G-3 GLO = 40 chains or 2640	T BLOGMFIELD" = 3180.59 Ft. or 3181.8	2 Ft. & 3180.43 Ft. (GPS-	MEA) 70 FILT
C. Description of monument for G-2 I replaced the found ½" In County Remonumentatio S03°E 40.54' Set PK & R S68°W 100.87' Set PK & N59°W 213.48' SE come N22°E 82.22' SW corner	corner and accessories established to perpetron Rod inside a 3/" Iron Pipe with 5/8" x 2 n, PS #17623 in a new Monument Box emon Washer West face Power Pole Remon Washer NW face Power Pole r of house #1988 of house #1989	4" Iron Rod w/2" diameter	brass cap stamped Oakland Brass cap stamped Oakland OF MICHON HUSTON KENNEDY
The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available professional Surveyors as the best availab			
Surveyor's Michignan License No	. 0 17623	Date 3-7-9	8 PROFESCIONAL SUPPLIANTANTANTANTANTANTANTANTANTANTANTANTANTA

:|