

COPY

LIBER 1959EPC408

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

(County)

Located In:

Corner Code #

West Bloomfield Township

## 1. Public Land Survey

T2N R9E G-12

T R

T R

T R

2. Property Controlling  
In Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

\$9.00 MISC RECORDING  
\$2.00 REMONUMENTATION  
02/24/1999 09:09:43 A.M. RECEIPT# 3390  
PAID RECORDED - OAKLAND COUNTY  
G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 2-17-99 JS  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

Register of Deeds Stamp &amp; File Num

## 4. Lot No. Recorded Plat

SECTION

## 5. Private Claims

I, Huston K. Kennedy, in a field survey on January 1, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	
1													
2		6		5			4		3		2		1
3													
4		7		8			9		10		11		12
5													
6		18		17			16		15		14		13
7													
8		19		20			21		22		23		24
9													
10		30		29			28		27		26		25
11													
12		31		32			33		34		35		36
13													

## A. Description of original monument and accessories and/or subsequent restoration:

1817-GLO Carpenter, D.S.; Set Post 12" Hickory S78°E 85 Links; 6" Sugar N80 ¾°W 16 ½ Links

1.) 1972-Cantrell, PS #5782; LCRC L.5940, Pgs. 266 &amp; 267 - Fnd a plow point

2.) 1993-DeKeyser, PS #30080; LCRC L.14208, Pg.847 - Fnd a PK Nail

3.) Carlson, PS #14759 Survey L.5940, Pg.264 - Used same wit as 1972 LCRC

4.) 1984-Smith, PS #21582; Survey L.8662, Pg.378 - Object found not stated

5.) 1988-Milletics, PS #29249; Survey L.10363, Pg.373 - Object found not stated

6.) 1962-Oakland County Road Commission Unrecorded Witnesses - Fnd a plow point

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1999-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a PK Nail 2 feet West of the existing centerline of Farmington Road extending to the North & South, which has a bituminous surface, also found a ½" Iron Rod in a Monument Box 2.08 feet to the East.

Witnesses from LCRC #2 were used to recover and verify the location of the found PK Nail.

I accepted the found PK Nail as the best evidence of the original corner position.

Field Measurements see back side of LCRC

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-12 I replaced the found PK Nail with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped "Oakland County"

Remonumentation, PS #17623 in a new Monument Box

S10°E 167.86' Set Mag Nail &amp; Remon Washer SW face Power Pole

S23°W 136.27' Set Mag Nail &amp; Remon Washer SE face 11" Poplar

N37°E 47.83' Set Mag Nail &amp; Remon Washer NW face Power Pole

N47°W 191.85' Set Mag Nail &amp; Remon Washer SW face 8" Pine

N80°E 2.08' Fnd a ½" Iron Rod in a Monument Box

East 59.69' Fnd ½" Iron Rod

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by

Date

2-17-99

Surveyor's Michigan License No.

17623

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYOR'S, JAN. 28, 197

REVISED MAY 14, 197

REVISED JAN., 196

REVISED OCT., 196

FE 24 99 06 28 70

900 FILE  
200