

COPY

LIBER 19595PC410

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

(County)

Located In:

Corner Code #

West Bloomfield Township

## 1. Public Land Survey

T2N R9E G-13

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

SECTION

## 4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_

## 5. Private Claims \_\_\_\_\_

\$9.00 MISC RECORDING  
\$2.00 REMONUMENTATION  
02/24/1999 09:09:43 A.M. RECEIPT# 3390  
PAID RECORDED - OAKLAND COUNTY  
G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS.

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 2-17-99 JS  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

Register of Deeds Stamp &amp; File Number

I, Huston K. Kennedy, in a field survey on January 9, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

## A. Description of original monument and accessories and/or subsequent restoration:

1817-GLO Carpenter, D.S.; Set Post 14" White Ash S37 1/4° E 9 Links; 6" Red Budd N7 1/2° W 17 Links

1.) 1972-Cantrell, PS #5782; LCRC L.5940, Pgs. 266 &amp; 267 - Fnd a PK Nail

2.) 1993-DeKeyser, PS #30080; LCRC L.14208, Pg.847 - Fnd a PK Nail

3.) 1997-Ward, PS #22445; LCRC (G-1 Farmington Twp.) L.17466, Pg.839 - Fnd a 1/2" Iron Pipe in a Monument Box

4.) Warner, Cantrell &amp; Padmos, Inc., Survey L.5940, Pg.264 - Fnd a PK Nail, used same wit as 1972 LCRC

5.) 1974-Feldhauser Associates, Unrecorded Survey - Object found not stated, no witnesses

6.)

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1999-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a PK Nail in the existing centerline of 14 Mile Road extending to the East & West, which has a bituminous surface, also 21 feet West of the existing centerline of Farmington Road extending to the South, which has a bituminous surface, and in the existing centerline of Farmington Road extending to the North, which has a bituminous surface. Corner common to Sections 3 & 4, T1N, R9N, Farmington Township (G-1) is located 21.26 feet to the West.

Witnesses from LCRC #2, 3 & "VILLAGE SQUARE NO. 2" were used to recover and verify the location of the found PK Nail.

I accepted the found PK Nail as the best evidence of the original corner position.

Field Measurements see back side of LCRC

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13 I replaced the found PK Nail with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland County  
Remonumentation, PS #17623 in a new Monument Box

N21°E 67.19' Fnd Mag Nail w/Oakland County Remon Washer PS #22445 SE face Power Pole

N63°W 99.08' Fnd Mag Nail w/Oakland County Remon Washer PS #22445 SW face Power Pole

S19°E 32.92' Set Mag Nail &amp; Remon Washer SW face Power Pole

S63°W 73.72' Set Mag Nail &amp; Remon Washer NW face Guide Pole

N72°W 145.87' Cut "X" top of bolt on Fire Hydrant

West 21.26' corner common to Sections 3 &amp; 4, T1N, R9E, Farmington Twp., (G-1)

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by:

Date

2-19-99

Surveyor's Michigan License No.

17623

