UBER 19489 PG 261

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in

Corner Code # Located in: <u>Oakland</u> West Bloomfield Township (County) R9E T<u>2N</u> 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Property in Sec. , Recorded Plat 4. Lot No. 5. Private Claims

I. Huston K. Kennedy in a field survey on October 27 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the lines of the latestar. Primary of land Research and the current manual of survey instructions of the latestar. United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:


NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

\$ 7.00 HISCELLANEOUS RECORDING \$ 2.00 REHONUMENTATION RECEIPTH 80A 21 JAN 99 9128 A.M. RECORDED - DAKLAND COUNTY PAID G.WILLIAM CADDELL CLERK/REGISTER OF DEEDS

> Compliance with ACT 345, P.A. 1990

1-13-55 APPROVED ON: -DAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number



- Description of original monument and accessories and/or subsequent restoration: 1817-GLO Carpenter, D.S.; Set Post 14" White Oak N20 1/2" W 60 Links; 16" White Oak S17°E 89 Links 1.) 1978-Postiff, PS #8894; LCRC L.6709, Pg.528 - Set a PK Nail
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a PK Nail located in the existing centerline of Middlebelt Road extending to the North & South, which has a bituminous surface. Also found a second PK Nail N28°E 2.26 feet, which I did not accept.

Witnesses from LCRC #1 & "FRUEHAUF FARMS" were used to recover and verify the location of the found PK Nail.

I accepted the found PK Nail as the best evidence of the original corner positon.

FIELD MEASURMENTS BETWEEN

GLO = 39.99 chains or 2639.34 Ft. "FRUEHAUF FARMS" + Parcels (Sec 23) = 2652.80 Ft. POWER HORN ESTATES" + "OAKWOOD SUBDIVISION" + Parcel (Sec 26) = 2852.81 Ft. 2651.96 Ft. (GPS)

K-9 to K-8

GLO = 40 chains or 2640.00 Ft. WEST BLOOMFIELD CREST" + "WALNUT GROVE" + Parcels K-9 to K-10 (Sec 25) = 2708.12 Ft. "OAKWOOD SUBDIVISION" + "POWDER HORN ESTATES" (Sec 26) = 2707.20 Ft. 2703.97 Ft. (GPS-MEA) MANAGER OF AICHONING

K-9 to L-9 No GLO, corner falls in a lake

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. HUSTON

K-9 I replaced the found PK Nall with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oaklang County Rehidral tentage
#17623 in a new Monument Box
\$87°W 60.07' Fnd 4" diameter Concrete Monument
N84°E 34.12' End 12" [See 12"] S27°E 69.17' Cut "x" on top of bolt on Fire Hydrant SUNVEYOR
N28°E 2.26' Fnd PK Noil

N84°E 34.12' Fnd ½" Iron Rod N85°E 60.58' Fnd ½" Iron Rod S67°W 31.42' Set Mag Nail & Remon Washer SE face Power Pole

FICE SOLUTION OF THE PROPERTY OF THE PROPERTY

S67°W 31.42' Set Mag Nail & Remon Washer SE face Power Pole S31°W 75.00' Set Mag Nail & Remon Washer SE face Power Pole	A No Catalities of the Angelogy
The selected location is accepted by me and is generally accepted	by Professional Surveyors as the best available evidence of
The selected location is accepted by me and is generally accepted	DA LIDICOGGGGGGGGGGGGGGGGGGGGGGGGGGGGGGGGGGG
the position of the original corner.	

Signed by: Surveyor's Michignan License No. 1-14-99