

LIBER 19595PC415

FE 24 99 NH 2875

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland
(County)

Located in: Corner Code #
West Bloomfield Township

\$9.00 MISC RECORDING
\$2.00 REMONUMENTATION
02/24/1999 09:10:04 A.M. RECEIPT# 3390
PAID RECORDED - OAKLAND COUNTY
G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS

1. Public Land Survey

T2N R9E K-11

T R

T R

T R

S T R

2. Property Controlling in Section

S

T

R

3. Miscellaneous Property in Sec.

S

T

R

S

T

R

SECTION

Compliance with
ACT 345, P.A. 1998
APPROVED ON: 2-17-99 JS
OAKLAND COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat

5. Private Claims

I, Huston K. Kennedy, in a field survey on September 28, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4			3		2		1	
3													
4	7		8		9			10		11		12	
5													
6	18		17		16			15		14		13	
7													
8	19		20		21			22		23		24	
9													
10	30		29		28			27		26		25	
11													
12	31		32		33			34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:
1817-GLO Carpenter, D.S.; No post was set, no witnesses

- 1.) 1994-Millettics, PS #29249; LCRC L.15050, Pg.488 - Fnd a 1/2" Rerod in a Monument Box
- 2.) 1994-Millettics, PS #29249; Survey L.15073, Pg.127 - Object found not state, no witnesses
- 3.) 1962-Oakland County Road Commission unrecorded witnesses - Fnd a Spike
- 4.) Oakland County Road Commission unrecorded witnesses - Fnd a Spike

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a 1/2" Iron Rod in a Monument Box located in the existing centerline of Middlebelt Road extending to the North & South, which has a bituminous surface, and in the existing centerline of Maple Road extending to the East & West, which has a bituminous surface.

Witnesses from LCRC #1 were used to recover and verify the location of the found 1/2" Iron Rod in a Monument Box.

I accepted the found 1/2" Iron Rod in a Monument Box as the best evidence of the original corner position.

Field measurements see back side of LCRC

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
K-11 I replaced the found 1/2" Iron Rod with a 5/8" x 24" Iron Rod w/2" diameter brass cap. Remonumentation, PS #17623 in a existing Monument Box
N48°W 67.97' Set Mag Nail & Remon Washer SW face Power Pole
N48°E 74.83' Set Mag Nail & Remon Washer SE face Traffic Pole
S46°E 83.23' Set Mag Nail & Remon Washer NW face Power Pole
S47°W 94.60' Set Mag Nail & Remon Washer SE face Power Pole

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by:

Date

2-18-99

Surveyor's Michigan License No.

17623

