

MAY 16 1996

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMISSION

<u>Oakland</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 4N R 9E	K-1
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

\$ 7.00 MISCELLANEOUS RECORDING  
\$ 2.00 REMONUMENTATION  
23 MAR 95 9:48 A.M. RECEIPT# 14B  
PAID RECORDED - OAKLAND COUNTY  
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS  
Compliance with  
ACT 345, P.A. 1990  
APPROVED ON: 2-15-95  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE  
Register of Deeds Stamp & File Number

I, James J. Scharl, in a field survey on December 12, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Post set in 1817 G.L.O. survey; S 34½°E 343 lks, 10" B Oak; S 37-2/3°W 363 lks, 8" B Oak.	LCRC, L14495, P189-190
LCRC, L8160, P519	Stonerock, 1991
Hubbell, 1982	Found 1/2" capped iron
Found 3/4" rerod	*N16°E 43.84' PK/flasher 54" Willow
*N15°E 43.89' N/C SE face 56" Willow	*N87°E 20.15' PK/flasher 28" Cherry
*S87°E 19.89' N/C S root 24" Cherry	*S24°E 41.58' PK/flasher 40" Oak
*S30°E 41.83' N/C NE root 34" Oak	*S70°W 66.88' PK/flasher PP

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered 7/8" rerod 2.26 ft north of Township line. LCRC's and measurements east, south and west verify the location of the 7/8" rerod as the section corner referencing surveys in this area. A new corner was set 2.26 ft south on the Township line, holding the E-W location of the 7/8" rerod.

Witnesses Found

\*N 15°E 45.06' Nail/tag W face 56" Willow  
\*N 87°E 20.18' PK/tag S face 24" Cherry  
\*S 30°E 41.18' PK/tag W face 40" Oak  
\*S 70°W 67.36' Nail/cap W face MBT pole

\*Confirms LCRC witness

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set concrete monument with O.C. remonumentation brass cap.  
N 15°E 47.28' PK/remon tag W face 56" Willow  
N 87°E 20.75' PK/remon tag S face 24" Cherry  
S 30°E 39.25' PK/remon W face 40" Oak  
S 70°W 65.88' PK/remon tag S face MBT pole

The position of the recovered 7/8" rerod was established using improper procedures and is referenced to give public notice of its erroneous existence. The selected location is a careful and faithful reestablishment of the position of the original corner. This corner is also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990.

Signed by James J. Scharl Date February 8, 1995  
Surveyor's Michigan License No. 19843

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

