tibir 19758PC492



LAND CORNER RECORDATION CERTIFICATE 106306

Filing Requirement of Act 74, Mich. P.A.LTERO 19758 PAGE *7.00 MISC RECORDING

\$7.00 MISC RECORDING

\$2.00 REMONUMENTATION

03/30/1999 01:03:22 P.M. RECEIPT# 12968

PAID RECORDED - OAKLAND COUNTY

OF THE PROPERTY OF For corners in 0akland Located In: Corner Code # (County) G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS 1. Public Land Survey T5N R 8E R Compliance with R ACT 345, P.A. 1990 TATEM 2. Property Controlling APPROVED ON: 11-05-98 in Section T R OAKLAND COUNTY REMONUMENTATION 3. Miscellaneous WAR Z I 2000 PEER GROUP COMMITTEE Property in Sec. Register of Deeds Stamp & File Numb SECTION , Recorded Plat 3 I, <u>Timothy J. Hart</u>, in a field survey on <u>3-16</u>, 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 5 conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 8 9 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 10 11 A. Description of original monument and accessories and/or subsequent restoration: Post set in 1823 G.L.O. survey, 14" B. Oak N 46°E 16 1ks; 12" W. Oak S 06°W 11 1ks. A) OCRC, 1936 2"x2" stake set in brick & tile (3) B) OCRC, 1958, fd 3/4" pipe in bricks (3) C) LCRC, L10890, P360, 1989, Dekeyser, 1989, fd pipe (3) No. 2315.

No. 2315.

e manner. D) LCRC, L15305, P872, 1994, Bonno, fd 1" pipe (4) E) LCRC, L14849, P722, 1994, Ward, fd iron pipe (4) (n) number of witnesses confirmed NOTE: LCRC, L8084, P450, Williams & LCRC, L14922, P776, Thompson, witness pipe 5.86 ft west of the accepted corner. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner; Recovered a 1" pipe (pipe "A") at the centerline intersection of Jossman running north and south, and McGinnis running west. Another 1" pipe (pipe "B") was recovered 5.86 ft west of pipe "A". A tree/fence row runs east from the corner. Location of pipe "B" was rejected due to lack of supporting evidence. Witnesses Recovered N 35°W 55.20' Nail/tag 32332 E 20" Cherry(A,B,C,D,E) N 15°E 50.14' Nail/tag 32332 W 24" Oak (C,D) N 15°E 50.06' Nail/tag 22445 W 24" Oak (E) S 55°W 76.93' PK nail N 30" Box Elder (B) 28.41' Nail/tag 32332 S 26" Walnut (A,B,D,E) S 25°E 83.42' PK na11 E 24" Walnut (A S 55°W 76.16' Nail/tag N 30° Box Elder (C,D,E) (1) indicates O.C.R.C or LCRC confirmed C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" rerod with O.C. remonumentation brass cap, replacing 1" iron pipe. 55.22' PK/remon tag E. 20" Cherry N 35°W State Plane Coordinates 50.04' PK/remon tag W. 24" Oak 28.34' PK/remon tag S. 26" Walnut 83.42' PK/remon tag S. 24" Walnut N 481304.9068 N 15°E E 13358398.9779 S 25°E S 55°W 76.20° PK/remon tag N. 30° Box Elder The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345~of P.A. 1990. Visa Date Surveyor's Michigan License No