SURVEY & EMONUMENTATION

JAN 182001

STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

RECTION LAND CORNER RECORDATION CERTIFICATE 21 DEC 2000 3:24:53 PM Filing Requirement of Act 74, Mich. P.A. 1970 For corners in JOSEPH'E. MERTEN Oceana Located In: REGISTER OF DEEDS Corner Code # (County) 101046 T16NR 18W J-3 Public Land Survey R R T R 2. Property Controlling in Section S R Miscellaneous S Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims 1 2 July 7, 2000 3 J. Randolph Hepworth in a field survey on , 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the 5 United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, 7 recovered, found as expressed below: 8 Not more than 2 corners, all in the same town and range, may be recorded 9 on this certificate. 10 11 1 A. Description of original monument and accessories and/or subsequent restoration: J-3 1/4 CORNER COMMON TO SECTIONS 2 & 11 T16N, R18W PENTWATER TOWNSHIP GLO John Hodgson 1838 SET POST 10" Pine Pentwater Beach Addition No. 1, HA Grant, 1902 Pentwater Beach Addition No. 4, HA Grant, 1904 S65°W 12 lks 12" W. Oak N23°W 21 lks Lake Michigan is west 52.28 ch. LCRC #100068, J. M. Carlson, 5-11-70, Fd 3/4" Pipe 3" above ground 1) 9" Oak N17°W 12.11 10" N. Pine S37°W 15.21 3) 9" Oak \$84°E 14.93 OCRC Witness Book 1973. See LCRC#100068 Witnesses Oceana County Remonstration Recorded Survey, Jkt#166, S. Barnett #16923, 11/19/74 Peer Group Reviewed & Approved -00 Timber Shores Sub'd, Dennis Dunlap # 21759, 1986 McCall Estates Sub'd, R. Hays #25847, 1988 Hegworth. J. Randakin Unrecorded Survey, JR Hepworth #26457, 6/23/90 Fd 1/2" Iron Oment Cost LCRC #100546, R. Hays #25847, 11/23/94 Found a 1/2" re-rod on side hill, south of road, from previous surveys. 4) 15" Oak S81°W 32.32' 5) 19" W Oak N27°W 46.58' Į, ŗ 2:11 5) 7) N27°W 46.58 10" W Pine 53.52 N42°E Hepworth Iron HERMANI 35.05 West LAND Recorded Survey, Jkt # 554, R. Hays #25847 , 11/23/94 (See LCRC # 100546) SUBJETOR Recorded Survey, Jkt # 676, R. Hays #25847, 9/14/98 1:0-26437 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. I found a 1/2" fron on the side of a steep hill and 25'm/l south of centerline of E-W Road. This road was reconstructed in the late 1970's and the Carison pipe was probably destroyed then with all witnesses. All Hays witnesses to this 1/2" Iron are standing and measure OK. No ancient corner evidence will be found in this highly disturbed area. This 1/2" Iron fits ties to McCall Estates Subd. And Pentwater Beach Addition No. 1. I accept the 1/2" Iron as the best available evidence of the position of the original corner. No evidence is known to me that would lead me to believe the corner should be at another location. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" and "26457" in place of the Iron which was placed in the hole beside the monument. 12" Oak 16" W Pine Set 60d spk above ex. PK Nail N Face 269°az 32.231 **EDM** Ex. 60d spk E Face 334°az 46.56 EDM Ex. 60d spk **NW Face** 12" W Pine 42° az 53.49 **FDM** 7) Ex. JRH 1/2" Iron/cap Ex. JRH 1/2" Iron/cap 273°az 35.05 **EDM** 93°az EDM December 15, 2000 Signed by Date 26457 Surveyor's Michigan License No