## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: OGEMAW (County)		Located In			Corner Code #					
1. Public Land Survey		T T	21N 21N	R 3E R 3E	C-5					
Property Controlling in Section	s	T		R						
Miscellaneous     Property in Section	s s	T T		R						
4. Lot No:	Recorded Plat:									
5. Private Claims:										
I, <u>Carl T. Kiiskila</u> , in a field survey on <u>June 16, 2009</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in										

the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

4	А В	С	٥	E F	G	н	l J	K	L M
				$\top$	Π"	$\top$		Т	$\Box$
2	fi	$\top$	-5- 	7-1	$\top$	- 3 — 	<del> </del>	+	1
3		$\dashv$	+		+	+	┼┼	+	$\vdash$
4	<u>⊢</u> ₹.	-	- 8			_10	<u> </u>	┿	12
5	-	<u></u>	•		-	$\bot$		<u> </u>	Ш
6	18.	$\perp$	-17-	16	<u> </u>	 -15़—	14-	┷	 13
7	-	$\dashv$	-	$\perp$	_	+-	$\bot\bot$		Ш
8	  19·	_	-20	21		-2 <u>2</u>	23-	<u> </u>	24
9	Н	-	+	-	-	_	$\vdash \vdash$	_	
10	<u></u> 30.	-	-29-	28	-	 -2 <u>?</u> —	26-	<del> </del>	] 25—
11	$\vdash$	-	+	-	+	_	$\vdash$	4	<u> </u>
12	-31-	$\perp$	-32-	33	_	-34	  35-	4-8	36—
13						Щ			

Register of Deeds Stamp & File Number

- A. Description of original monument and accessories and/or subsequent restoration:
- C-5 Section Corner common to sec's 7,8,17,18, T21N,R3E

1846 - GLO - B.F.Hall - Set post corner Sections 7,8,17,18. Hemlock 10" N57°E 23 links Cedar 12" N30°W 04 links

1974 - Cert. of Survey - L.2, p.15 - Norman C. Caldwell, P.S.#12018 -

Shows corner on survey. Shows distances to North and East.

1974 - Corner References - L.2, p.16 - Norman C. Caldwell,
P.S.#12018 - Fd. "T" iron and RLS cap.

N04°E 16.0' 4" Cedar S39°E 7.5' 10" Hemlock (NBT) S78°W 10.0' 11" Tamarack (NBT)

1974 – L.C.R.C. – L.1, p.66 – Norman C. Caldwell, P.S.#12018 – Same info as L.2, p.16.

1976 - Cert. of Survey - L.2, p.147 - Robert L. Higgins, P.S.#21570 -NW corner of sec. 17, T21N,R3E, fd. 1/2" bar of record.

D-5 Quarter Corner common to sec's 8&17, T21N.R3E

1846 - GLO - B.F.Hall - Set quarter sec. post.

Y. Pine 16" S43°E 36 links Y. Pine 13" N75°E 29 links

1974 - Cert. of Survey - L.2, p.15 - Norman C. Caldwell, P.S.#12018 -Set corner by single proportion between C5 & E5.

1974 - Corner References - L.2, p.16 - Norman C. Caldwell,

P.S.#12018 - Set 1/2" bar & RLS cap. Placed DNR post alongside.

N50°W 17.2' 10" Oak (NBT) N80°E 15.25' 10" Oak (NBT) S18°E 42.25' 10" Oak 1974 – L.C.R.C. – L.1, p.66 – Norman C. Caldwell, P.S.#12018 – Same info as L.2, p.16.

1976 - Cert. of Survey - L.2, p.138 - Robert L. Higgins, P.S.#21570 - N 1/4 corner of sec. 17, T21N,R3E, fd. 1/2" bar of record

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
- C-5 Section Corner common to sec's 7,8,17,18, T21N,R3E

Fd. downed cedar guard post and three of Caldwell's witnesses. Fd. no evidence of any iron with extensive searching. Fd. corner fence post with wire near position. Reestablished position of missing iron from the remains of Caldwell's three witnesses. Set stamped 4" dia. DNR alum. cap on 1"x72" galvanized pipe. Found no other evidence to dispute the location for the corner. Accepted reestablished DNR monument as the best available evidence for the position of the original corner.

D-5 Quarter Corner common to sec's 8&17, T21N,R3E

Found 1/2" CIR#12018 per L.C.R.C., L.1,pg.66, 10" below grade. Cedar guard post with location tag was on NW side of found iron. NE/SW 2track drive is West 10'. Accepted found iron as a careful and faithful reestablishment of the position of the original corner. Found no other evidence to dispute location for corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-5 Section Corner common to sec's 7,8,17,18, T21N,R3E

D-5 Quarter Corner common to sec's 8&17, T21N,R3E

Set stamped 4" Dia. Alum. DNR cap on 1"x72" galv. Pipe

N12°E 16.02' to fd. nail in face of bottom blaze of 6" Cedar N60°E 6.53" to set N&T on S side 8" Cedar ('XBT') S23°E 7.96' to set N&T on W side 11" Hemlock (7.55' to face)

S68°W 23.82' to set N&T on N side 11" Cedar ('XBT') N35°W 13.87' to set N&T on NE side 5" Cedar ('XBT') S82°W 9.9' to face of 12" Tamarack stump

Set Blue Carsonite Post 1' North

Signed by:

Surveyor's Michigan License No.:

33981

Wit: N46°E 20.09' to set N&T on W side 10" Oak S20°W 42.99' to fd N&T#28417 on W side 15" R.Oak N46°W 17.54' to set N&T on N side 14" W.Oak N03°W 48.91' to set N&T on W side 14" W. Pine Painted top of Cedar Guard post with red paint.

Set stamped 4" Dia. Alum. DNR cap on 1"x36" galv. Pipe

OF MUCHICAN -13-09 CARL **UISKILA** LAND SURVEYOR

No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971
Revised May 14, 1975
Revised Jan. 1983

Revised Oct. 1995