

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Ogemaw  
(County)

Located In

Corner Code #

1. Public Land Survey	T	23N	R	2E	E-9
	T	23N	R	2E	F-9
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on November 19, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

E-9 GLO -James H. Mullett D.S. 1846

Set post

Wit: Aspen 8 N83°E 24 links

Aspen 6 S27°W 4 links

F-9 GLO- James H. Mullett D.S. 1846

Set Qr. Section Post

Wit: Y. Pine Stub 18 N18°E 23 links

Y. Pine Stub 16 S33°E 48 links

L.C.R.C - L.1, p.205 - Larry Cavanagh P.S.#17614 -  
1975 - Found 1/2" Bar and Cap

Recorded Survey - L.4,p. 427 - Duane F. Ledy  
P.S.#21575 - 1990 - Set 1/2" CIR#21575 - by single  
proportionate measurement.

Wits: N40°W 56.04' 24" W. Oak  
S45°E 52.32' 20" Maple  
S10°W 39.22' 22" Triple Oak  
S22°W 32.62' 13" Maple



B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E-9 Found 1/2"x18" rebar with broken plastic cap and all of Cavanagh wits. (Did not use Triple Oak, bad condition) Corner is 2' North of E-W C/L gravel road and is inline with C/L gravel road to north. Accepted found rebar as the best available evidence of the position of the original corner.

F-9 Found 1/2" CIR#21575 4' North of E-W C/L gravel road. Accepted found 1/2"CIR as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-9 Found 1/2" rebar with broken cap, replaced with 1"x3' galvanized pipe with P.S. cap#33981 down 0.6' below grade.  
Wit: 25" White Oak N73°E 78.70' (fd. nail on NW side)  
27" Red Maple S50°E 52.99' (fd. nail on SW side)  
14" Red Maple S10°W 32.67' (fd. nail on E side)  
22" White Oak N40°W 56.87' (fd. nail on W side)  
Set Blue Carsonite Post with Loc. Tag 33' South

F-9 Found 1/2" CIR#21575 drove a 1"x3' galvanized pipe with P.S. cap#33981 over found iron 0.6' below grade.  
Wit: 12" Red Oak N55°E 44.44' (set N&T on SE side)  
10" White Pine S8°E 53.33' (set N&T on W side)  
6" White Pine S45°W 56.49' (set N&T on NW side)  
14" Red Oak N66°W 77.12' (set N&T on S side)  
Set Blue Carsonite Post with Loc. Tag 33' South

Signed by:

*Carl T. Kiiskila*

Date:

6-17-09

Surveyor's Michigan License No.:

33981