MAR 02 2001

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

F	cornere	*

Ontonagon County Located in: Corner Code # 1. Public Land Survey T46N R39W T46N **R40W** R Ŧ R T 2. Property Controlling T R S Т in Section R 3. Miscellaneous S T R Property in Sec. S R

UDITH D. ROEHM Ontonagon County C 5/366 1 of 1 EM Date 01/03/2001 14:38:18 3.00 ECORDING FEE:

4. Lot No.


, Recorded Plat

5. Private Claims

f. Joseph C. Domitrovich, in a field survey on July 12, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

13 A. Description of original monument and accessories and/or subsequent restoration:



Register of Deeds Stamp & File Number

(A - 3) Section Corner common to Section 6 & 7 T46N, R39W, and Sections 1 & 12, T46N, R40W.

1847 - John Burt set a post with ties:

16" Black Ash S 20°E 40 links 12" Spruce N 45°W 12 links 20" W. Pine N 82°E 13 links

1986 - Dick Drahn, P.S. 21564, re-established this corner with a 2" x 12" concrete filled pipe with a 3" brass cap. He blazed 3 new bearing trees and added a reference monument.

6" Aspen	N 34°W	66.98'
4" Red Maple	N 16°E	113.50
8" White Spruce	S 77°W	132.91
6' Steel Sign Post	S 43°E	32.56'
R.M.	S 42°E	31.25'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. The concrete filled pipe called for by Dick Drahn had been removed by road reconstruction. I recovered 2 of Dick Drahn's bearing trees and his reference monument. The 6' Aspen is now dead and broken off. I re-established the section corner from Dick Drahn's record bearing objects.

Research on file with County Remonumentation Representative.

12-19-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 24" iron pin with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T46N, R39W, R40W; S. 6, S. 1, S. 7, S. 12; 2000; P.S. 37273. Ties: OF MICH

4" Spruce N 51°E S 40°F 31.25' R.M. (Existing) S 75°W 132.91' (Existing) 9" Spruce 12" Poplar N 26°W 99.49' (Existing)

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.

DOMITROVICH

LAND SURVEYOR

No. 37273

LANG